

### Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities Permit Number: AR0020702 Reporting Period(Month/Year): March 2018

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions			Action(s) Taken	Ultimate Discharge Location
Cause(s) of SSO	SSO Impact	SSO Description	Action(s) Taken	Ultimate Discharge Location
CO-Construction		NEAH-No Evidence of Adverse of Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	D-Debris	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DJ-Ditch
HC-Hydro Clean	G-Grease LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering PN-Public Notification	PA-Paved Area CB-Contained in Building

  

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location

*Rich Plummer*  
Signature of Cognizant or Ranking Official

4-16-18  
Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."