

# Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities Permit Number: AR0020702 Reporting Period(Month/Year): May 2015

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		SSO Impact		Action(s) Taken		Ultimate Discharge Location		
CO-Construction	D-Debris	NEAH-No Evidence of Adverse of Environmental Impact		WO-Work Order		CR-Creek/Stream/River (please specify)		
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact		EC-Environmental Cleanup		DI-Ditch		
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill		HC-Hydro Cleaned		DR-Drop Inlet		
R-Rainfall	RG-Roots & Grease			HR-Hand Rodded		GR-Ground Surface		
RO-Roots	V-Vandalism			EN-Referred to Engineering PN-Public Notification		PA-Paved Area CB-Contained in Building		
Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
2200 Lee st.	11-Jun	5/13/2015	5/13/2015	Undetermined	R	NEAH	EC	GR

Signature of Cognizant or Ranking Official

Date June 8, 2015

"I certify under penalty of law that this document and all attachments were prepared under my direction of supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."