


Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities
 Permit Number: AR0020702
 Reporting Period(Month/Year): August 2016

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions		
Cause(s) of SSO	SSO Impact	Action(s) Taken
CO-Construction	NEAH-No Evidence of Adverse of Environmental Impact	WO-Work Order
E-Equipment Failure HC-Hydro Clean	G-Grease	EC-Environmental Cleanup HC-Hydro Cleaned
	LF-Line Failure/Break	
R-Rainfall	RG-Roots & Grease	HR-Hand Rodded
RO-Roots	V-Vandalism	EN-Referred to Engineering PN-Public Notification
		DI-Ditch DR-Drop Inlet GR-Ground Surface PA-Paved Area CB-Contained in Building

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
817 Bates	Cleanout	08/18/2016	08/19/2016	Undetermined	R	NEAH	EC	DI



 Signature of Cogizant or Ranking Official

Date 9-7-16

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."