

Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities Permit Number: AR0020702 Reporting Period(Month/Year): September 2023

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO	Summary Report Code Descriptions				Action(s) Taken	Ultimate Discharge Location		
	SSO Impact	NEAH-No Evidence of Adverse of Environmental Impact	OEHC-Observed or Evidence of Human Contact	EFK-Evidence of Fish Kill				
CO-Construction	D-Debris				WO-Work Order	CR-Creek/Stream/River (please specify)		
E-Equipment Failure	G-Grease				EC-Environmental Cleanup	DH-Ditch		
HC-Hydro Clean	LF-Line				HC-Hydro Cleaned	DR-Drop Inlet		
	Failure/Break							
R-Rainfall	RG-Roots & Grease				HR-Hand Rodded	GR-Ground Surface		
RO-Roots	V-Vandalism				EN-Referred to Engineering	PA-Paved Area		
					PN-Public Notification	CB-Contained in Building		
Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
499 19th St.	4-74A	9/30/2023	9/30/2023	30	RG	NEAH	HC,EC	GR

[Signature]

10/2/23

Signature of Cognizant or Ranking Official _____ Date
"I certify under penalty of law that this document and all attachments were prepared under my direction of supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."