## Sanitary Sewer Overflow Monthly Report

The state of the s

		j	Sum	mery Report Code D	Descriptions				
Cause(s) of SSO		SSO Impact				Action(s) Taken	Ultimat	Ultimate Discharge Location	
The street species of		The second secon				i i			
CO-Construction	D-Debris	NEAH-No Evidence of Adverse of Environmental				WO-Work Order	CR-Creek/S	CR-Creek/Stream/River (please specify)	
F. C. L. C. A. C. Miller	0.0	Impact   OEHC-Observed or Evidence of Human Contact						DI-Ditch	
-Equipment Failure	G-Grease					EC-Environmental Cleanur			
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill				HC-Hydro Cleaned		DR-Drop Inlet	
R-Rainfall	RG-Roots & Grease					HR-Hand Rodded	G	GR-Ground Surface	
RO-Roots	V-Vandalism				·	EN-Referred to Engineering		PA-Paved Area	
The same of the sa						PN-Public Notification		CB-Contained in Building	
No de la		Ï				1		· · · · · · · · · · · · · · · · · · ·	
Location	Manhole #	State Date of	End Date of	Estimated	Cause of S	SO Environmental	Action(s) Taken	Ultimate Discharge	
The state of the s	* **	sso	sso	Volume (in gallons)		Impact	to Address SSO	Location	
Meyers St. Duck pond	040005	12/21/2013	12/21/2013	Undetermined	R	NEAH	HC,EC	CR	
6th & Boswell	020439	12/22/2013	12/22/2013	150	D	/ NEAH	HC,EC	CR	
	:			** .					
: -						<u> </u>			
	·   · · · · · · · · · · · · · · · · · ·						<b>.</b>		
	<u> </u>	<b>—</b>				, , , , , , , , , , , , , , , , , , ,			
<u> </u>	•		,	,					
		*		* * ** *				· · · · · · · · · · · · · · · · · · ·	
		2 .				•			
						7.4			
* * * * * * * * * * * * * * * * * * * *		ļ .							
		¥	<u> </u>	* ***	<del> </del>	l i			
and the second of the second of the second		1	,			3			
		!						<b></b>	
		ļ., ļ.			•				
			. ,			<del></del>			
The same as a	· · <u> </u>				<u> </u>	l l	J	•	

"I certify under penalty of law that this document and all attachments were prepared under my direction of supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Batesville Wastewater Treatment Plant
500 River Bank Road
Batesville, Arkansas 72501

15 JAW 2019 PM 3 I



ADEQ Water Division-Enforcement Branch 5301 North Shore Drive North Little Rock, AR 72118-5317

72118531799

այրերդերիրը գերավերի հերևություն և հերևաների հերև