

## Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities Permit Number: AR0020702 Reporting Period(Month/Year): August 2013

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse of Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
891 Bryant	5-91	8/19/2013	8/19/2013	1000	RG	NEAH	EC,HC	GR

  
 Signature of Cognizant or Ranking Official

9/10/2013  
 Date

"I certify under penalty of law that this document and all attachments were prepared under my direction of supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

**Batesville Wastewater Treatment Plant**

500 River Bank Road  
Batesville, Arkansas 72501

LITTLE ROCK, AR 72202

19 SEP 2013 PM 12



ADEQ  
Water Division-Enforcement Branch  
5301 Northshore Drive  
North Little Rock, AR 72118-5317

72118531799

