BATESVILLE WASTEWATER TREATMENT PLANT

500 River Bank Road Batesville, Arkansas 72501 Phone (870)-698-2442 Fax 870-698-2443 wwsuper@cityofbatesville.com

April 10, 2013

NPDES ENFORCEMENT DIVISION Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, Arkansas 72118

RE: NPDES AR0020702 - AFIN: 32-00044_

This letter is to notify your office that the Batesville Wastewater Treatment Plant exceeded its discharge limit for the month of March 2013 on the following parameters.

		Reported Value Monthly Avg.	Permit Limit Monthly Avg.	Reported Value Weekly Avg.	Permit Limit Weekly Avg.	
a.	TSS Concentration	52 mg/l	40 mg/l	67 mg/l	60 mg/l	
b.	TSS Loading	2278 pounds	1467.8 pounds	•		

These violations occurred because of porous plate damage to the filters and extensive rainfall over the last few months. We have made several repairs to the filters, however the lagoons still remain high. As you may be aware, we are currently under construction to expand the wastewater treatment plant with an expected completion date of June 2014. If you have any other questions or comments feel free to call anytime.

Sincerely;

Eugene Townsley
Plant Superintendent

Cc: Mr. Damon Johnson P.E.

March 2012

RECEIVED

1 1 NI Sic

Facility Name: Batesville Water Utilities

Richetter	4-2-13
ignature of Cognizan) or Ranking Official	Date
11) modifier and an annual to a face of the state of an annual and all although a read a company of the state of	

			Sumi	mery Report Code	Descriptions				
Cause(s) of SSO		SSO Impact				Action(s) Taken		Ultimate Discharge Location	
CO-Construction	D-Debris	NEAH-No Evidence of Adverse of Environmental				WO-Work Order		CR-Oreek/Stream/River (please specify)	
-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact		EC-E	EC-Environmental Cleanup		DI-Ditah		
HC-Hydro Classo	LF-Line Føllure/Break	EFK-Evidence of Fish Kill				HC-Hydro Cleaned		DR-Drap Inlet	
R-Rainfall	RG-Roots & Grease					HR-Hand Rodded		GR-Ground Surface	
RO-Roots	V-Vandalism					EN-Referred to Engineering		PA-Paved Area	
						PN-Public Notification		ontained in Building	
Location	Manhole #	State Date of	End Date of	Estimated	Cause of SSO	Environmental	Action(s) Taken	Ultimate Discharge	
		\$\$0	SSO	Volume (in gallons)		Impact	to Address SSO	Location	
720 20TH STREET	MH 4-20	3/8/2012 ,	3/8/2012	350	R	NEAH I	WO, EC, HC	CR	
550 GREG DR.	MH 1-42A	3/8/2012	3/8/2012	450	R	NEAH I	WO, EC, HC	CA, DI	
		<u> </u>							
						,			
						1			
		•				1		· <u>-</u>	
								· · · · · · · · · · · · · · · · · · ·	
						,			
									

Sanitary Sewer Overflow Monthly Report

AR0020702

Reporting Period(Month/Year):

Permit Number:

I certify under penalty of law that this document and all attachments were prepared under my direction of supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the persons or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant pensities for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Batesville Wastewater Treatment Plant
500 River Bank Road
Batesville, Arkansas 72501



NPDES Enforcement Division ADEQ 5301 Northshore Drive North Little Rock, AR 72118

72118531799

saa ակվերիկիակիադիակիակին ses