

Sanitary Sewer Overflow Monthly Report

Facility Name: City of Flippin


Permit Number: AR0021717

Reporting Period (Month/Year): September 2013

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		
		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease			
HC-Hydro Clean	LF-Line Failure/Break	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
R-Rainfall	RG-Roots & Grease	EFK-Evidence of Fish Kill	HC-Hydro. Cleaned	DR-Drop Inlet
RO-Roots	V-Vandalism		HR-Hand Rodded	GR-Ground Surface
			EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location


 Signature of Cognizant or Ranking Official

10-15-2013
Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."



"A Place For All Seasons"

Post Office Box 40
Flippin, Arkansas 72634

NPDES Enforcement Section
ADEQ
5301 Northshore Dr.
North Little Rock, AR 72118-5317



02 1P
0001805447 OCT 15 2013
MAILED FROM ZIP CODE 72634
\$ 000.66⁰