### **Thomas Harrington (adpce.ad)**

From: Terry Long <eswwtp@yahoo.com>
Sent: Tuesday, March 5, 2024 3:07 PM

**To:** Water-Enforcement-Report; Richard Healey (adpce.ad); Thomas Harrington (adpce.ad)

**Cc:** Simon Wiley; Zane Lewis; Spencer Briggs

**Subject:** AR 0021865 AFINL 08-00036

Attachments: BacT sampling FEBRUARY 28 2024.pdf

### ADEQ Water Enforcement,

Please find the attached lab results with chain of custody from the samples pulled from Leatherwood Creek on Wednesday February 28, 2024.

Moving forward, we will continue to collect and analyze samples from the eight (8) locations specified and we will be forwarding those results when received.

If you have any questions, please feel free to contact me.

Thank you,

### Terry

Terry Long, Plant Manager Eureka Springs WWTP 100 Highway 23 N. Eureka Springs, AR 72632 479-253-7410 - Office 479-738-7035 - Cell 479-253-6974 - Fax eswwtp@yahoo.com

Eureka Springs WWTP Eureka Springs Public Works Dept. 3174 E. Van Buren Eureka Springs, AR 72632 479-253-9600 - Office 479-253-6974 - Fax

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2402020210

Customer Name : EUREKA SPRINGS WWTP @ CREEK

Customer Number: 2856 Report Date: 03/04/24 Sample Date : 02/28/24

Sample Time: 0924

Sample Type : GRAB WATER
Sample From : #1 WWTP & CREEK

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order :

Laboratory Analysis Quality Assurance Analysis Precision Accuracy Date Time By Parameter Result Notes Ouantity Method % RPD % Recovery 02/28 1610 AMJ E. Coliforms 10.0 /100ml 06/2012 Colilert18 0.00 N/A \*

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2402020211

Customer Name : EUREKA SPRINGS-CREEK@835 HWY 23N

Customer Number: 2849
Report Date: 03/04/24

Sample Date : 02/28/24

Sample Time : 0930

Sample Type : GRAB WATER
Sample From : #2 CRK @ HWY 23N

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order :

Analysis	Laboratory Analysis			Quality Assurance	
Date Time By	Parameter E. Coliforms	Result Notes Quantity 52.0 /100ml	Method 06/2012 Colilert18	Precision % RPD 0.00	Accuracy % Recovery N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

ontrol	Number.	2402020212
	Mannat:	44U4U4U414

Customer Name : EUREKA SPRINGS-POWERLINE 1/2 PLT

Customer Number: 2850 Report Date: 03/04/24 Sample Date : 02/28/24

Sample Time : 0934 Sample Type : GRAB WATER

Sample From : #3 CRK @ POWERLINE

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order :

Laboratory Analysis Quality Assurance Analysis Precision Accuracy Date Time By Parameter Result Notes Method % RPD % Recovery 02/28 1610 AMJ E. Coliforms 41.0 /100ml 06/2012 Colilert18 0.00 N/A \*

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services Co., Inc

K

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2402020213

Customer Name : EUREKA SPRINGS-CREEK@HWY 23 N

Customer Number: 2851 Report Date: 03/04/24 Sample Date : 02/28/24

Sample Time : 0938

Sample Type : GRAB WATER
Sample From : #4 CRK @ HWY 23 XING

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order: Purchase Order:

Analvsis		Laboratory Analysis		Quality 1	Assurance
Date Time By	Parameter E. Coliforms	Result Notes Quantity 51.0 /100ml	Method 06/2012 Colilert18	Precision % RPD 0.00	Accuracy % Recovery N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

ontrol	Number.	2402020214
	Munnoer:	2402020214

Customer Name : EUREKA SPRINGS-UPSTREAM WWTP

Customer Number : 2852 Report Date : 03/04/24 Sample Date : 02/28/24

Sample Time : 0924
Sample Type : GRAB WATER

Sample From : #5 CREEK UPSTREAM

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order : Purchase Order :

Laboratory Analysis Quality Assurance Analysis Precision Accuracy Date Time By Parameter Result Method 움 RPD % Recovery 02/28 1610 AMJ E. Coliforms 20.0 /100ml 06/2012 Colilert18 0.00 N/A \*

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2402020215

Customer Name : EUREKA SPRINGS-CREEK @ GASKINS

Customer Number: 2853 Report Date : 03/04/24 Sample Date : 02/28/24

Sample Time : 0941

Sample Type : GRAB WATER Sample From : #6 CRK @ GASKINS Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order :

Purchase Order :

Analysis	Laboratory Analysis					Quality Assurance	
Date Time By 02/28 1610 AMJ	Parameter E. Coliforms	Result < 10.0 /100	Notes _	Quantity	Method 06/2012 Colilert18	Precision % RPD	Accuracy & Recovery
,		1 20.0 7 200	,111		00/2012 COIIIeILI8	0.00	N/A *
* QA data sho	wn is from a different sam	ple or standard on	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

ontrol	Number.	2402020216
CIICLOI	MUMBET:	2402020210

Customer Name : EUREKA SPRINGS-CR@HWY 187 BRIDGE

Customer Number: 2854
Report Date: 03/04/24

Sample Date : 02/28/24

Sample Time : 0948

Sample Type : GRAB WATER
Sample From : #7 CRK@ HWY187 BRDGE

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order :

<u>Laboratory Analysis</u>				Quality A	<u>Assurance</u>	
Analysis	The second by the second	79. 71.			Precision	Accuracy
<u>Date Time By</u> 02/28 1610 AMJ	Parameter	Result Notes	Quantity	Method	% RPD	% Recovery
02/28 1610 AMU	E. Coliforms	10.0 /100ml		06/2012 Colilert18	0.00	N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2402020217

Customer Name : EUREKA SPRINGS-CR@MARTIN MARINE

Customer Number: 2855

Customer Number: 2855 Report Date: 03/04/24 Sample Date : 02/28/24

Sample Time : 0955

Sample Type : GRAB WATER
Sample From : #8 CRK MARTIN MARINE

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order:

Purchase Order :

Laboratory Analysis					Quality A	Assurance	
Analysis						Precision	Accuracy
<u>Date Time By</u>	<u>Parameter</u>	Result	<u>Notes</u>	<u>Quantity</u>	<u> Method</u>	% RPD	% Recovery
02/28 1610 AMJ	E. Coliforms	75.0 /100m	nl		06/2012 Colilert18	0.00	N/A

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services 6.



### Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com

Phone: 501-221-2565 Fax: 501-221-1341



#### Environmental Services Com y, Inc. Northwest Branch 1107 Century Springdale, AR 72764

## **CHAIN OF CUSTODY**

Phone 479-750-1170 Fax:: 479-750-1172 Project Information Client Information Requested Parameters Permit/Project #: AR#0021865/ AFIN 08-00036 Company Name: Eureka Springs Address: Purchase Order #: 3174 E. Van Buren Eureka Springs, AR 72632 Sampler Name(s): Telephone: (479) 253-7410 FAX: (479) 253-6974 and Signature(s): ESWWTP@YAHOO.COM ESC Client Number: 1505-Effluent 1508-Influent S Sample Identification Sample Collection Sample Containers Identification ESC Control # Date Time Type Matrix Type Volume I Preservative # ш 2402020210 2128/26 #1 WWTP & Creek 1592U **GRAB** Water Sterile 100 m Na<sub>z</sub>S<sub>2</sub>O<sub>3</sub> Х 36,42014 -93,73453 #2 Creek at 835 Hwy 23 N 7 14 1 7 0 1 0 7 11 0930 **GRAB** Water Sterile Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х 100 m 36.42497 -93.73669 7402020212 2/2shy 0934 #3 Creek at powerline **GRAB** Water Sterile 100 m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х 36.42518 -93.73646 #4 Creek at Hwy 23 crossing 7.467020213 Ø938 **GRAB** Water Sterile 100 m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х 36.4398 -93.72906 2018/14 0924 140101020214 #5 Creek upstream GRAB Water Sterile Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> 100 m Х 36.42021 -93.73473 Received By: (Signature and Printed Name) Dale Custody Seals: Relinquished By: (Signature and Printed Name) 1235 Used? Intact? Received By: (Signature and Printed Name) Date Turnaround Records for Lab By / Signature and Printed Name Regular Special Relinquished By: (Signature and Printed Name) Date Ware samples properly preserved: 1235 Yes FLOW DATA Field Test Comments: Time Analyst Result Result Units Analyst: :Ha Time: Temp.: Reading: DO: Debris: Units: Cool all samples to 6 degrees C. This Document is Page \_\_ (1 of 2 Chlorinated? Yes

J\FORMS\CHAIN.XLS

### Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com

Fax: 501-221-1341 Phone: 501-221-2565



Environmental Services Complete , Inc. Northwest Branch 1107 Century Springdale, AR 72764

**CHAIN OF CUSTODY** 

Phone 479-750-1170 Fax:: 479-750-1172 Project Information Requested Parameters Client Information AR#0021865/ AFIN 08-00036 Permit/Project #: Eureka Springs Company Name: Purchase Order #: 3174 E. Van Buren Address: Eureka Springs, AR 72632 Sampler Name(s): (479) 253-7410 Telephone: (479) 253-6974 FAX: and Signature(s): ESWWTP@YAHOO.COM ESC Client Number: 1505-Effluent 1508-Influent Sample Identification Sample Collection Sample Containers Volume Preservative ші Matrix Type ESC Control # Date Time Type Identification Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х 2412020215 0041 **GRAB** Water Sterile 100 m #6 Creek at Gaskins B6.426440 -93.443830 #7 Creek at Hwy 187 Bridge 7,40 20 20 21 (4 **6948** Na<sub>z</sub>S<sub>2</sub>O<sub>3</sub> Х **GRAB** Water Sterile 100 m 36,4456 -93,74420 #8 Creek at Martin Marine W (2020212 Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> X 6955 **GRAB** Water Sterile 100 m 36,47349 -93,76037 Relinquished By: (Signature and Printed Namo)

W. R. L. M. BALEWINE Custody Seals: Received By: (Signature and Printed Name) 1235 Used? Intact? Date Received By: (Signature and Printed Name) Special Regular ed for Lawy. (Signature and Printed Name) OZ/28 Were samples properly preserved: Relinquished By: (Signature and Printed Name) Date Yes No / FLOW DATA / Field/Test Analyst Units Result Result Comments: Analyst: pH: Temp.: Time: Reading: DO: Units: Debris: Chlorinated? Yes No This Document is Page (2 of 2 Cool all samples to 6 degrees C.