Thomas Harrington (adpce.ad)

From: Terry Long <eswwtp@yahoo.com>
Sent: Wednesday, March 20, 2024 7:55 AM

To: Water-Enforcement-Report; Richard Healey (adpce.ad); Thomas Harrington (adpce.ad)

Cc: Simon Wiley; Zane Lewis; Spencer Briggs

Subject: AR 0021865 AFIN: 08-00036

Attachments: BacT sampling MARCH 15 2024.pdf

ADEQ Water Enforcement,

Please find the attached lab results with chain of custody from the samples pulled from Leatherwood Creek on Friday March 15, 2024.

Moving forward, we will continue to collect and analyze samples from the eight (8) locations specified and we will be forwarding those results when received.

If you have any questions, please feel free to contact me.

Thank you,

Terry

Terry Long, Plant Manager Eureka Springs WWTP 100 Highway 23 N. Eureka Springs, AR 72632 479-253-7410 - Office 479-738-7035 - Cell 479-253-6974 - Fax eswwtp@yahoo.com

Eureka Springs WWTP Eureka Springs Public Works Dept. 3174 E. Van Buren Eureka Springs, AR 72632 479-253-9600 - Office 479-253-6974 - Fax

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020170

Customer Name : EUREKA SPRINGS WWTP @ CREEK

Customer Number : 2856 Report Date : 03/19/24 Sample Date : 03/15/24

Sample Time : 0802

Sample Type : GRAB WATER
Sample From : #1 WWTP & CREEK

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order: Purchase Order:

	Laboratory Analysis					Assurance
Analysis Date Time By	Parameter	Result Notes	Quantity	Method	Precision % RPD	Accuracy <pre>% Recovery</pre>
03/15 1338 AMJ	E. Coliforms	238.0 /100ml		06/2012 Colilert18	20.58	N/A *

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020171

Customer Name : EUREKA SPRINGS-CREEK@835 HWY 23N

Customer Number: 2849 Report Date : 03/19/24 Sample Date : 03/15/24

Sample Time: 0849

Sample Type : GRAB WATER Sample From : #2 CRK @835 HWY 23N

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order: Purchase Order :

Laboratory Analysis						Assurance	
Analysis <u>Date</u> <u>Time</u> <u>By</u>	Parameter	Result	Notes	Quantity	Method	Precision % RPD	Accuracy & Recovery
03/15 1338 AMJ	E. Coliforms	1354.0 /100ml			06/2012 Colilert18	20.58	N/A *

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020172

Customer Name : EUREKA SPRINGS-POWERLINE 1/2 PLT

* QA data shown is from a different sample or standard on the same date.

Customer Number: 2850 Report Date: 03/19/24 Sample Date : 03/15/24

Sample Time : 0852

Sample Type : GRAB WATER
Sample From : #3 CRK @ POWERLINE

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order : Purchase Order :

Analysis		Laboratory A	<u>malysis</u>			Quality	Assurance
Date Time By	Parameter	Resul	t Notes	Quantity	Method	Precision RPD	Accuracy % Recovery
03/15 1338 AMJ	E. Coliforms		0 /100ml		06/2012 Colilert18	20.58	N/A *
				,			
					<u> </u>		
					ş T		

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020173

Customer Name : EUREKA SPRINGS-CREEK@HWY 23 N

Customer Number: 2851 Report Date: 03/19/24 Sample Date : 03/15/24

Sample Time : 0857

Sample Type : GRAB WATER Sample From : #4 CRK@ HWY 23 XING Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order : Purchase Order :

	Laboratory Analysis					Quality Assurance	
Analysis					Precision	Accuracy	
<u>Date Time By</u>	<u> Parameter</u>	<u>Result</u> <u>Notes</u>	Quantity	Method	% RPD	% Recovery	
03/15 1338 AMJ	E. Coliforms	52.0 /1.00ml		06/2012 Colilert18	20.58	N/A *	

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020174

Customer Name : EUREKA SPRINGS-UPSTREAM WWTP

Customer Number: 2852 Report Date: 03/19/24 Sample Date : 03/15/24

Sample Time : 0802 Sample Type : GRAB WATER

Sample From : #5 CREEK UPSTREAM

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order : Purchase Order :

Laboratory Analysis					Quality 1	Assurance
Analysis <u>Date</u> <u>Time</u> By	Parameter	Result N	Jahan Ourseliku	75 - 15 - 7	Precision	Accuracy
		209.0 /100ml	Notes Quantity	Method 06/2012 Colilert18	<u>% RPD</u> 20.58	<pre>% Recovery N/A *</pre>
03/13 1336 AUD	E. COLLIGINIS	209.0 /100ml		06/2012 Colliert18	20.58	N/P

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020175

Customer Name : EUREKA SPRINGS-CREEK @ GASKINS

Customer Number: 2853 Report Date : 03/19/24

Sample Date : 03/15/24

Sample Time : 0902 Sample Type : GRAB WATER

Sample From : #6 CREEK @ GASKINS

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order :

Purchase Order :

Analysis		Laboratory Analys:	<u>.s</u>			Quality .	<u>Assurance</u>
Date Time By 03/15 1338 AMJ	Parameter E. Coliforms	Result 62.0 /100	<u>Notes</u> _	Quantity	Method 06/2012 Colilert18	Precision <u>% RPD</u> 20.58	Accuracy <u>% Recovery</u> N/A *
					`		,
* 07 11	um is from a different sa		. •				

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020176

Customer Name : EUREKA SPRINGS-CR@HWY 187 BRIDGE

Sample Date : 03/15/24 Sample Time: 0908

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Customer Number: 2854

Sample Type : GRAB WATER

Work Order :

Report Date : 03/19/24

Sample From: #7 CRK@ HWY187 BRDGE

Purchase Order :

Ampleodo	Laboratory Analysis					Quality Assurance	
Analysis Date Time By 03/15 1338 AMJ	Parameter E. Coliforms	Result Notes 41.0 /100ml	Quantity	Method 06/2012 Colilert18	Precision % RPD 20.58	Accuracy <u>% Recovery</u> N/A *	

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020177

Customer Name : EUREKA SPRINGS-CR@MARTIN MARINE

Customer Number: 2855 Report Date: 03/19/24 Sample Date : 03/15/24

Sample Time : 0916

Sample Type : GRAB WATER
Sample From : #8 MARTIN MARINE

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order: Purchase Order:

<u>Laboratory Analysis</u>					Quality 1	Assurance
Analysis		_			Precision	Accuracy
<u>Date Time By</u>	Parameter	ResultNotes	Quantity	<u>Method</u>	%RPD	% Recovery
03/15 1 338 AMJ	E. Coliforms	121.5 /100ml		06/2012 Colilert18	20.58	N/A

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Envisormental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com

Fax: 501-221-1341



Environmental Services Com, v. Inc. Northwest Branch 1107 Century Springdale, AR 72764

CHAIN OF CUSTODY

Phone 479-750-1170 Fax:: 479-750-1172 Phone: 501-221-2565 Requested Parameters Project Information Client Information AR#0021865/ AFIN 08-00036 Eureka Springs Permit/Project #: Company Name: Purchase Order #: Address: 3174 E. Van Buren Eureka Springs, AR 72632 Sampler Name(s): (479) 253-7410 Telephone: FAX: (479) 253-6974 ESWWTP@YAHOO.COM and Signature(s): **ESC Client Number:** 1505-Effluent 1508-Influent Coli Sample Identification Sample Collection Sample Containers Volume Preservative # ESC Control # Matrix Type ш Identification Date Time Type #1 WWTP & Creek 2403020170 3/10/24 0802 **GRAB** Sterile Na₂S₂O₃ X Water 100 m 36.42014 -93.73453 3/05/24 0849 Х #2 Creek at 835 Hwy 23 N 12403020171 GRAB Water Sterile 100 m Na₂S₂O₃ 36.42497 -93.73669 2403020172 #3 Creek at powerline **GRAB** Water Sterile 100 m Na₂S₂O₃ X 36.42518 -93.73646 3/15/14 0857 #4 Creek at Hwy 23 crossing 24 03 02 0173 **GRAB** Na₂S₂O₃ 1 X Water Sterile 100 m -93.72906 36.4398 0200 2403020174 X #5 Creek upstream **GRAB** Water Sterile 100 m Na2S2O3 1 36.42021 93.73473 Received By: (Signature and Printed Name) Custody Seals 1107 Used? Intact? Received By: (Signature and Printed Name) Turnaround: Regular Special Received for Use By: (Signature and Printed Name) Relinquished By: (Signature and Printed Name) Were samples properly preserved: Date 03/15/24 Yes No Field Test FLOW DATA Result Analyst Result Units Comments: Analyst: pH: Time: Temp.: DO: Reading: Units: Debris: Chlorinated? Yes This Document is Page Cool all samples to 6 degrees C.

Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com

Fax: 501-221-1341



Environmental Services Company, Inc. Northwest Branch 1107 Century Springdale, AR 72764

CHAIN OF CUSTODY

Phone 479-750-1170 Fax:: 479-750-1172 Phone: 501-221-2565 Requested Parameters Client Information Project Information AR#0021865/ AFIN 08-00036 Permit/Project #: Company Name: Eureka Springs Purchase Order #: 3174 E. Van Buren Address: Eureka Springs, AR 72632 URLIAM BALON TINE Sampler Name(s): Telephone: (479) 253-7410 FAX: (479) 253-6974 and Signature(s): ESWWTP@YAHOO.COM ESC Client Number: 1505-Effluent 1508-Influent Coli Sample Collection Sample Containers Sample Identification # ESC Control # Volume Preservative Date Time Matrix ш Identification Type Type 2403020175 0900 #6 Creek at Gaskins **GRAB** Water Sterile 100 m Na₂S₂O₃ 1 X 86.426440 -93.443830 #7 Creek at Hwy 187 Bridge 1403020174 1 X GRAB Water Sterile 100 m Na₂S₂O₃ 36.4456 -93.74420 0916 #8 Creek at Martin Marine 7413070177 Х GRAB Water Sterile Na₂S₂O₃ 1 100 m 36.47349 -93.76037 Received By: (Signature and Printed Name) Custody Seals: MILLAM BOLERA 1007 Used? Intact? Received By: (Signature and Printed Name) Turnaround Date Regular Special 03/15/24 Were samples properly preserved: Relinquished By: (Signature and Printed Name) Received for Lab By/(Signature and Printed Name) Kelin No /FLOW DATA Field Test Time Analyst Result Result Units Comments: Analyst: pH: Temp.: Time: DO: Reading: Units: Debris: This Document is Page Chlorinated? Yes No (2 of 2 Cool all samples to 6 degrees C.