#### **Thomas Harrington (adpce.ad)**

From: Terry Long <eswwtp@yahoo.com>
Sent: Wednesday, March 20, 2024 7:55 AM

**To:** Water-Enforcement-Report; Richard Healey (adpce.ad); Thomas Harrington (adpce.ad)

**Cc:** Simon Wiley; Zane Lewis; Spencer Briggs

**Subject:** AR 0021865 AFIN: 08-00036t

Attachments: BacT sampling MARCH 18 2024.pdf

#### ADEQ Water Enforcement,

Please find the attached lab results with chain of custody from the samples pulled from Leatherwood Creek on Monday March 18, 2024.

Moving forward, we will continue to collect and analyze samples from the eight (8) locations specified and we will be forwarding those results when received.

If you have any questions, please feel free to contact me.

Thank you,

#### Terry

Terry Long, Plant Manager Eureka Springs WWTP 100 Highway 23 N. Eureka Springs, AR 72632 479-253-7410 - Office 479-738-7035 - Cell 479-253-6974 - Fax eswwtp@yahoo.com

Eureka Springs WWTP Eureka Springs Public Works Dept. 3174 E. Van Buren Eureka Springs, AR 72632 479-253-9600 - Office 479-253-6974 - Fax

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479) 750-1170 Fax (479) 750-1172

Control Number: 2403020179

Customer Name : EUREKA SPRINGS WWTP @ CREEK

Customer Number: 2856 Report Date : 03/19/24 Sample Date : 03/18/24

Sample Time : 1158

Sample Type : GRAB WATER Sample From : #1 WWTP & CREEK Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order:

<u>Laboratory Analysis</u> Analysis						Assurance
	Da	T 11			Precision	Accuracy
Date Time By	<u>Parameter</u>	Result Notes	Quantity	<u> Method</u>	<u> </u>	% Recovery
03/18 1550 OKP	E. Coliforms	20.0 /100ml		06/2012 Colilert18	66.67	N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020180

Customer Name : EUREKA SPRINGS-CREEK@835 HWY 23N

Sample Date : 03/18/24 Sample Time : 1101

Collected By: WILLIAM BALENTI

Customer Number: 2849

Sample Type : GRAB WATER

Delivery By : WILLIAM BALENTI

Report Date : 03/19/24

Sample From: #2 CREEK 835 HWY 23N

Work Order : Purchase Order :

7 7 '		Laboratory Analysis			Quality 2	Assurance
Analysis <u>Date Time By</u> 03/18 1550 OKP	Parameter E. Coliforms	Result <u>Notes</u> 109.0 /100ml	Quantity	Method 06/2012 Colilert18	Precision <u>% RPD</u> 66.67	Accuracy <u>% Recovery</u> N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020181

Customer Name : EUREKA SPRINGS-POWERLINE 1/2 PLT

Customer Number: 2850 Report Date : 03/19/24 Sample Date : 03/18/24

Sample Time : 1103 Sample Type : GRAB WATER

Sample From : #3 CRK @ POWERLINE

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order :

<b>2 3 1</b>	Laboratory Analysis						Assurance
Analysis <u>Date Time</u> <u>By</u>	<u> Parameter</u>	Result	<u>N</u> otes	Quantity	Method	Precision % RPD	Accuracy % Recovery
03/18 1550 OKP	E. Coliforms	131.0 /100m]	L		06/2012 Colilert18	66.67	N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020182

Customer Name : EUREKA SPRINGS-CREEK@HWY 23 N

Customer Number: 2851 Report Date: 03/19/24 Sample Date : 03/18/24

Sample Time : 1116

Sample Type : GRAB WATER Sample From : #4 CRK @ HWY 23 XING Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order : Purchase Order :

Laboratory Analysis Quality Assurance Analysis Precision Accuracy Date Time By Parameter Notes Ouantity Method % RPD % Recovery 03/18 1550 OKP E. Coliforms 63.0 /100ml 06/2012 Colilert18 66.67 N/A \*

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479) 750-1170 Fax (479) 750-1172

Control Number: 2403020183

Customer Name : EUREKA SPRINGS-UPSTREAM WWTP

Customer Number: 2852 Report Date : 03/19/24 Sample Date : 03/18/24

Sample Time : 1158

Sample Type : GRAB WATER Sample From : #5 CREEK UPSTREAM Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order:

Laboratory Analysis				Quality Assurance		
Analysis					Precision	Accuracy
<u>Date Time By</u>	Parameter	Result Notes	Quantity	Method	% RPD	% Recovery
03/18 1550 OKP	E. Coliforms	74.0 /100ml		06/2012 Colilert18	66.67	N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020184

Customer Name : EUREKA SPRINGS-CREEK @ GASKINS

Customer Number: 2853 Report Date: 03/19/24 Sample Date : 03/18/24

Sample Time : 1120 Sample Type : GRAB WATER

Sample From : #6 CREEK AT GASKIN'S

Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Work Order: Purchase Order:

	Laboratory Analysis					Quality Assurance	
Analysis <u>Date</u> <u>Time</u> <u>By</u> 03/18 1550 OKP	Parameter E. Coliforms	Result < 10.0 /100m	<u>Notes</u> _	Quantity	Method 06/2012 Colilert18	Precision % RPD 66.67	Accuracy % Recovery N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020185

Customer Number: 2854

Customer Name : EUREKA SPRINGS-CR@HWY 187 BRIDGE

Report Date : 03/19/24

Sample Date : 03/18/24

Sample Time: 1132

Sample Type : GRAB WATER

Sample From : #7 HWY 187 BRIDGE

Collected By: WILLIAM BALENTI Delivery By : WILLIAN BALENTI

Work Order :

Purchase Order:

n		Laboratory Analysis		Quality 1	Assurance
Analysis <u>Date</u> <u>Time</u> <u>By</u> 03/18 1550 OKP	Parameter E. Coliforms	Result Notes Quant	ity Method 06/2012 Colilert18	Precision <u>% RPD</u> 66.67	Accuracy <u>* Recovery</u> N/A *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2403020186

Customer Name : EUREKA SPRINGS-CR@MARTIN MARINE

Sample Date : 03/18/24 Sample Time : 1139 Collected By: WILLIAM BALENTI Delivery By: WILLIAM BALENTI

Customer Number: 2855

e : Eureka springs-cremartin marine ber : 2855

Sample Type : GRAB WATER

Work Order :

Report Date : 03/19/24

Sample From : #8 MARTIN MARINE

Purchase Order :

	Laboratory Analysis					Quality 2	Assurance
Analysis						Precision	Accuracy
<u>Date Time By</u>	Parameter	Result	Notes _	Quantity	Method	% RPD	% Recovery
03/18 1550 OKP	E. Coliforms	15.0 /100r	nl		06/2012 Colilert18	66.67	N/A

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Env., urnental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AF: 72211

Little Rock, AF 72215

website: www.esclabs.com



Environmental Services Company, Inc. Northwest Branch 1107 Century Springdale, AR 72764

#### CHAIN OF CUSTODY

Phone 479-750-1170 Fax:: 479-750-1172 Phone: 501-221-2565 Fa:c: 501-221-1341 Client Information Project Information Requested Parameters AR#0021865/ AFIN 08-00036 Permit/Project #: Company Name: Eureka Springs 3174 E. Van Buren Purchase Order #: Address: Eureka Springs, AR 72632 MILLIAM BALENTINE Sampler Name(s): Telephone: (479) 253-7410 FAX: (479) 253-6974 and Signature(s): ESWWTP@YAHOO.COM ESC Client Number: 1505-Effluent 1508-Influent Coli Sample Identification Sample Containers Sample Collection # Time Matrix Type Volume Preservative ші Identification ESC Control# Date ( Type 3/18/24 1158 Х #1 WWTP & Creek 2403020179 Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> **GRAB** Water Sterile 101) m 36,42014 -93,73453 #2 Creek at 835 Hwy 23 N 24 03020 ) & 6 3/18/24 11001 **GRAB** Water Sterile 101) m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> X 36.42497 -93.73669 2403020181 3/18/20 Na2S2O3 X #3 Creek at powerline 11003 **GRAB** Water Sterile 101) m 36.42518 -93.73646 #4 Creek at Hwy 23 cross ng 2403020182 3/18/14 **GRAB** Water Sterile 101) m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> X 36.4398 -93.72906 3/1824 1158 #5 Creek upstream 2403020183 **GRAB** Water Sterile 101) m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> X 36.42021 -93.70-7. 36.42021 -93.73473 Received By: (Signature and Printed Name) 3/18/24 1356 Used? Intact? Turnaround Received By: (Signature and Printed Name) Time Date Regular Special Reger leg for Lab By (Signatury and Printed Name) Were samples properly preserved Relinquished By: (Signature and Printed Name) Time Date Fielc/Test /FLOW DATA Time Analyst Units Result Result Comments: pH: Analyst: Time: Temp. DO: Reading: Units: Debris: This Document is Page Cool all samples to 6 degrees C. Chlorinated? Yes



# Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AF: 72211

Little Rock, AF 72215

website: www.esclabs.com



Environmental Services Company, Inc.
Northwest Branch
1107 Century
Springdale, AR 72764

CHAIN OF CUSTODY Phone 479-750-1170 Fax:: 479-750-1172 Phone: 501-221-2565 Fa:c: 501-221-1341 Requested Parameters Project Information Client Information AR#0021865/ AFIN 08-00036 Permit/Project #: Company Name: Eureka Springs 3174 E. Van Buren Purchase Order #: Address: Eureka Springs, AR 72632 VILLIAN BALGATING Sampler Name(s): Telephone: (479) 253-7410 FAX: (479) 253-6974 and Signature(s): ESWWTP@YAHOO.COM ESC Client Number: 1508-Influent 1505-Effluent Coli Sample Collection Sample Containers Sample Identification # Matrix Type Volume Preservative ші ESC Control# Date ( Time Type Identification 1120 Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> X #6 Creek at Gaskins 2403020184 **GRAB** Water Sterile 101) m B6.426440 -93.443830 #7 Creek at Hv/y 187 Bridge 2403020185 3/18/14 **GRAB** Sterile Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> X Water 101) m 36.4456 -93.74420 #8 Creek at Martin Marine 24030 2018 W **GRAB** Sterile 101) m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> X Water 36.47349 -93.76037 Received By: (Signature and Printed Name) Custody Seals: Used? Intact? Turnaround Received By: (Signature and Printed Name) Date Time Regular Special Received for Lab By: (Signature and Printed Name) Were samples properly preserved: Relinquished By: (Signature and Printed Name) 13510 Yes FLOW DATA Field Test Result Result Units Analyst Comments: Analyst: рН: Time: Temp.: Reading: DO: Debris: Units: This Document is Page 2 of 2 Chlorinated? Yes Cool all samples to 6 degrees C.

