#### Richard Healey (adpce.ad)

From: Terry Long <eswwtp@yahoo.com>
Sent: Tuesday, November 14, 2023 9:00 AM

**To:** Thomas Harrington (adpce.ad); Richard Healey (adpce.ad); Leslie Allen-Daniel (adpce.ad)

**Cc:** Simon Wiley; Zane Lewis; Spencer Briggs **Subject:** AR 0021865 AFIN 08-00036 CORRECTED

**Attachments:** BacT sampling Nov 10 2023.pdf

My apologies to all. I inadvertantly failed to attach the lab results to my previous email. Please accept my apologies for my oversight and I will endeavor to avoid this mistake moving forward.

Please find the attached lab results with chain of custody from the samples pulled from Leatherwood Creek on Friday 11/10/2023.

Moving forward, we continue to collect and analyze samples from the eight (8) locations specified and we will be forwarding those results when received.

If you have any questions, please feel free to contact me.

Thank you,

Terry

Terry Long, Plant Manager Eureka Springs WWTP 100 Highway 23 N. Eureka Springs, AR 72632 479-253-7410 - Office 479-738-7035 - Cell 479-253-6974 - Fax eswwtp@yahoo.com

Eureka Springs WWTP
Eureka Springs Public Works Dept.
3174 E. Van Buren
Eureka Springs, AR 72632
479-253-9600 - Office
479-253-6974 - Fax

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: Customer Name : Customer Number Report Date : 1	EUREKA SPRINGS WWTP @ CREE : 2856	Sample Date : 11/10/23  Sample Time : 1008  Sample Type : GRAB WATER  Sample From : #1 WWTP & CREEK	Collected By: WILLIAM BALENTI Delivery By : TERRY LONG Work Order : Purchase Order :
Analysis <u>Date Time By</u> 11/10 1415 RWS	Parameter	Laboratory Analysis  Result Notes Quantity  < 10.0 /100ml	Quality Assurance Precision Accuracy Method % RPD % Recover  06/2012 Colilert18
* ON data shoo	um is from a different samo	le or standard on the same date	

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

of s

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

	Control	Number:	2311020123
--	---------	---------	------------

Sample Date : 11/10/23

Collected By: WILLIAM BALENTI

Customer Name : EUREKA SPRINGS-CREEK@835 HWY 23N

Sample Time : 1019 Sample Type : GRAB WATER Delivery By : TERRY LONG

Customer Number: 2849

Work Order : Purchase Order:

Report Date : 11/13/23

Sample From: #2 CREEK 835 HWY 23N

Quality Assurance

Laboratory Analysis Precision Accuracy Analysis % RPD Quantity Method % Recovery Result Notes Date Time By Parameter 06/2012 Colilert18 11/10 1415 RWS E. Coliforms 189.0 /100ml

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

ontrol	Number:	2311020124
	TACHINGT.	ZJTTUZUTZT

Customer Name : EUREKA SPRINGS-POWERLINE 1/2 PLT

Sample Time: 1024

Collected By: WILLIAM BALENTI

Customer Number: 2850

FOREVE SEKINGS-FOMERHINE I/S EN

Sample Type : GRAB WATER

Sample Date : 11/10/23

Delivery By : TERRY LONG Work Order :

Report Date: 11/13/23

Sample From : #3 CREEK POWERLINE

Purchase Order :

		Laboratory Analysi	İs			Quality	Assuranc <u>e</u>
Analysis						Precision	Accuracy
<u>Date Time By</u>	Parameter	Result	Notes _	Quantity	Method	% RPD	% Recovery
11/10 1415 RWS		504.0 /100			06/2012 Colilert18		
•							
					İ		
t On data abor	m is from a different some	on standard on	the game	data	~		
" QA uata SIIO	wn is from a different samp	TE OF Prandard On	rite same	uace.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services Co., Inc.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020125 Customer Name : EUREKA SPRINGS-CREEK@HWY 23 N Customer Number : 2851 Report Date : 11/13/23	Sample Date : 11/10/23 Sample Time : 1030 Sample Type : GRAB WATER Sample From : #4 CREEK HWY 23	Deliver Work Or	ced By: WILLIAM BALENTI ry By : TERRY LONG rder : se Order :
Analysis  Date Time By Parameter  L1/10 1415 RWS E. Coliforms	Result Notes Quantity 121.0 /100ml	Method 06/2012 Colilert18	Quality Assurance Precision Accuracy % RPD % Recover

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services Co., Inc.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020126 Customer Name : EUREKA SPRINGS-UPSTREAM WWTP Customer Number : 2852 Report Date : 11/13/23	Sample Date : 11/10/23 Sample Time : 1012 Sample Type : GRAB WATER Sample From : #5 CREEK UPSTREA	Collected By: WILLIAM BALENTI Delivery By : TERRY LONG Work Order : M Purchase Order :
	Result Notes Quantity 94.5 /100ml	Method 06/2012 Colilert18  Quality Assurance Precision Accuracy % RPD % Recovery
* QA data shown is from a different sample or	standard on the same date.	

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services Co., Inc.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 231102	Number: 231102012	27
------------------------	-------------------	----

Sample Date : 11/10/23

Collected By: WILLIAM BALENTI

Customer Name : EUREKA SPRINGS-CREEK @ GASKINS

Sample Time: 1034

Delivery By : TERRY LONG

Customer Number: 2853

Sample Type : GRAB WATER

Work Order :

Report Date : 11/13/23

Sample From : #6 CREEK AT GASKINS

Purchase Order :

Analysis <u>Date Time By</u> 11/10 1415 RWS	Parameter E. Coliforms	Laboratory Analysi  Result  63.0 /100	Notes _	Quantity	Method 06/2012 Colilert18	Quality A Precision % RPD	Assurance Accuracy % Recovery
* QA data sho	own is from a different sam	ple or standard on	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control	Number:	2311020128
, O. I. I. O. I.	1101110001	2011020120

Customer Name : EUREKA SPRINGS-CR@HWY 187 BRIDGE

Sample Time: 1037

Collected By: WILLIAM BALENTI

Customer Number: 2854

Sample Time : 1037
Sample Type : GRAB WATER

Delivery By : TERRY LONG

Customer Number: 2854 Report Date: 11/13/23

Sample From : #7 CREEK 187 BRIDGE

Work Order : Purchase Order :

Analysis

Date Time By Parameter Result Notes Quantity Method % RPD % Recovery

11/10 1415 RWS E. Coliforms 41.0 /100ml 06/2012 Colilert18

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services Co., Inc



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

06/2012 Colilert18

Control	Mumber.	2311020129
COHCLOT	number:	Z3TT0Z0TZ9

11/10 1415 RWS E. Coliforms

Customer Name : EUREKA SPRINGS-CR@MARTIN MARINE

Sample Date : 11/10/23

Collected By: WILLIAM BALENTI

Customer Number: 2855

Sample Time: 1040

74.0 /100ml

Delivery By : TERRY LONG

Sample Type : GRAB WATER

Work Order : Purchase Order:

Report Date : 11/13/23

Sample From: #8 MARTIN MARINE

Quality Assurance Laboratory Analysis Precision Accuracy Analysis Quantity Method % RPD % Recovery Date Time By Result Notes

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

#### Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com

Phone: 501-221-2565

Fax: 501-221-1341



Environmental Services Company, Inc. Northwest Branch 1107 Century Springdale, AR 72764

# **CHAIN OF CUSTODY**

Phone 479-750-1170 Fax:: 479-750-1172 Project Information Requested Parameters Client Information AR#0021865/ AFIN 08-00036 Eureka Springs Permit/Project #: Company Name: Purchase Order #: 3174 E. Van Buren Address: Eureka Springs, AR 72632 WILLIAM BALENTINE Sampler Name(s): (479) 253-7410 Telephone: FAX: (479) 253-6974 and Signature(s): ESWWTP@YAHOO.COM 1508-Influent ESC Client Number: 1505-Effluent Coli Sample Identification Sample Collection Sample Containers Volume | Preservative # ESC Control# ші Identification Date Time Type Matrix Type 2311020122 1008 х #1 WWTP & Creek **GRAB** Water Sterile 100 m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> 36.42014 -93.73453 1/0/23 2311020123 #2 Creek at 835 Hwy 23 N **GRAB** Water Sterile 100 m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х 36,42497 -93,73669 71/10/23 2311020124 Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х #3 Creek at powerline 1004 **GRAB** Water Sterile 100 m 36.42518 -93,73646 11/10/23 #4 Creek at Hwy 23 crossing 1分00亿0亿 630 Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х **GRAB** Water Sterile 100 m 36.4398 -93.72906 2211020124 11/18/23 1012 Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> 1 Х #5 Creek upstream **GRAB** Water Sterile 100 m 36.42021 -93.73473 Relinquished By: (Signature and Printed Name) WILLIAM A PALENTINE Received By: (Signature and Printed Name)

Livy John
Received By: (Signature and Printed Name) 11/0/23 NO. TERM RLONG Used? Intact? Turnaround: Special Regular Received for Lab By: Signature and Printed Name) Relinquished By: (Signature and Printed Name) Were samples properly preserved Time PLOW DATA Field Test Time Analyst Result Result Units Comments: Analyst: pH: Time: Temp.: DO: Reading: Debris: Units: This Document is Page (1 of 2 Chlorinated? Yes No Cool all samples to 6 degrees C.



#### Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com



Environmental Services Company, Inc. Northwest Branch 1107 Century Springdale, AR 72764

## CHAIN OF CUSTODY

Phone 479-750-1170 Fax:: 479-750-1172 Phone: 501-221-2565 Fax: 501-221-1341 Project Information Requested Parameters Client Information AR#0021865/ AFIN 08-00036 Permit/Project #: Eureka Springs Company Name: Purchase Order #: Address: 3174 E. Van Buren Eureka Springs, AR 72632 WILLIAM BALENTIME Sampler Name(s): (479) 253-7410 Telephone: (479) 253-6974 FAX: ESWWTP@YAHOO.COM and Signature(s): ESC Client Number: 1505-Effluent 1508-Influent Coli Sample Collection Sample Identification Sample Containers Volume # Preservative ші Identification ESC Control # Date Time Type Matrix Type 1034 2211020127 #6 Creek at Gaskins **GRAB** Sterile 100 m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Х Water 86.426440 -93.443830 #7 Creek at Hwy 187 Bridge 2ろ川の701で分 11/0/12 1037 **GRAB** Sterile 100 m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> 1 X Water 36.4456 -93.74420 #8 Creek at Martin Marine ルスリルルリンク 11/10/13 1040 Х **GRAB** Sterile 100 m Na<sub>2</sub>S<sub>2</sub>O<sub>3</sub> Water 36.47349 -93.76037 11/0/13 Custody Seals 102 Used? BALGATNE Intact? Turnaround: Special Regular Relinquished By: (Signature and Printed Name) Received for Lab By: (Signature and Printed Name) Were samples properly preserved: Time Keny 110/23 FLØW DATA Field Test Time Analyst Units Result Result Comments: Analyst: pĤ: Temp.: Time: Reading: DO: Debris: Ünits: Chlorinated? Yes This Document is Page (2 of 2 Cool all samples to 6 degrees C.

