Richard Healey (adpce.ad)

From: Terry Long <eswwtp@yahoo.com>
Sent: Thursday, November 16, 2023 7:57 AM

To: Water-Enforcement-Report; Simon Wiley; Zane Lewis

Subject:AR 0021865 AFIN 08-00036Attachments:BacT sampling Nov 13 2023.pdf

ADEQ Water Enforcement,

Please find the attached lab results with chain of custody from the samples pulled from Leatherwood Creek on Monday 11/13/2023.

Moving forward, we continue to collect and analyze samples from the eight (8) locations specified and we will be forwarding those results when received.

If you have any questions, please feel free to contact me.

Thank you,

Terry

Terry Long, Plant Manager Eureka Springs WWTP 100 Highway 23 N. Eureka Springs, AR 72632 479-253-7410 - Office 479-738-7035 - Cell 479-253-6974 - Fax eswwtp@yahoo.com

Eureka Springs WWTP
Eureka Springs Public Works Dept.
3174 E. Van Buren
Eureka Springs, AR 72632
479-253-9600 - Office
479-253-6974 - Fax

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

'ontrol	Number:	2311020131
COULTOT	number:	73TT070T3T

Customer Name : EUREKA SPRINGS WWTP @ CREEK

Sample Date : 11/13/23

Collected By: WILLIAM BALENTI

Customer Number: 2856

Sample Time : 1353

Delivery By : TERRY LONG

Report Date : 11/15/23

Sample Type : GRAB WATER Sample From : #1 WWTP & CREEK Work Order : Purchase Order:

7		Laboratory Analys	is			Quality Precision	<u>Assurance</u> Accuracy
Analysis <u>Date</u> <u>Time</u> <u>By</u>	Parameter	Result	Notes _	Quantity	Method	% RPD	% Recovery
11/13 1630 NTR	E. Coliforms	10.0 /10	Oml		06/2012 Colilert18	11.54	N/A *
		,					
•							
,							
							•
	wn is from a different samp		. 1	7 .			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479) 750-1170 Fax (479) 750-1172

ontrol	Number.	2311020132
ハンエレエ ひエ	numer:	Z3TT0Z0T3Z

Sample Date : 11/13/23

Collected By: WILLIAM BALENTI

Customer Name : EUREKA SPRINGS-CREEK@835 HWY 23N

Sample Time: 1315

Delivery By : TERRY LONG

Customer Number: 2849

Sample Type : GRAB WATER

Work Order :

Report Date : 11/15/23

Sample From: #2 CREEK 835 HWY 23N

Purchase Order:

		<u>La</u>	aboratory Analys	<u>is</u>			Quality 1	
Analysis							Precision	Accuracy
Date Time By	Param	eter	Result	<u>Notes</u>	Quantity	Method	% RPD	% Recovery
11/13 1630 NTR	E. Coliforms		1723.0 /10	Oml		06/2012 Colilert18	11.54	N/A *
			,					
* QA data shov	wn is from a d	ifferent sample	or standard on	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Environmental Services Co., Inc.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020133

Sample Date : 11/13/23

Collected By: WILLIAM BALENTI

Customer Name : EUREKA SPRINGS-POWERLINE 1/2 PLT

* QA data shown is from a different sample or standard on the same date.

Sample Time : 1319

Delivery By : TERRY LONG

Customer Number: 2850

Sample Type : GRAB WATER

Work Order :

Report Date : 11/15/23

Sample From : #3 CREEK POWERLINE

Purchase Order:

70 7		<u>Laboratory Analysis</u>			<u>Quality</u> Precision	Assurance Accuracy
Analysis <u>Date</u> <u>Time</u> <u>By</u> 11/13 1630 NTR	Parameter E. Coliforms	Result Notes 2064.0 /100ml	Quantity	Method 06/2012 Colilert18	% RPD	% Recovery N/A *

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Analysis time indicates the time of Quality Assurance Plan on file with Arkansas Department of Environmental Quality. the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control	Number:	2311020134
COTTCTOT	munimer.	ムフエエしんしエフェ

Customer Name : EUREKA SPRINGS-CREEK@HWY 23 N

Customer Number: 2851 Report Date : 11/15/23

Sample Date : 11/13/23

Sample Time : 1323

Sample Type : GRAB WATER

Sample From: #4 CREEK HWY 23 XING

Collected By: WILLIAM BALENTI

Delivery By : TERRY LONG

Work Order : Purchase Order:

7		Laboratory Analysis	<u> </u>			Quality Precision	Assurance Accuracy
Analysis <u>Date</u> <u>Time</u> <u>By</u>	Parameter	Result	Notes _	Quantity	Method	% RPD	% Recovery
11/13 1630 NTR E		512.0 /100r			06/2012 Colilert18	11.54	N/A *
	· ·						
					į		
* OA data shown	is from a different samp	le or standard on t	he same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 231102	20135
------------------------	-------

Customer Name : EUREKA SPRINGS-UPSTREAM WWTP

Sample Date : 11/13/23 Sample Time : 1355 Collected By: WILLIAM BALENTI

Customer Number: 2852 Report Date: 11/15/23 Sample Type : GRAB WATER

Delivery By : TERRY LONG Work Order :

Sample From : #5 CREEK UPSTREAM

Purchase Order:

		Laboratory Analysi:	<u> </u>			<u>Quality <i>P</i></u> Precision	Assurance Accuracy
Analysis <u>Date</u> <u>Time</u> <u>By</u> 11/13 1630 NTR	Parameter E. Coliforms	Result < 10.0 /100	<u>Notes</u>	Quantity	Method 06/2012 Colilert18	* RPD 11.54	% Recovery N/A *
11/13 1030 1411	II. COLLICIMS	. 20.0 / 200	•••				,
* QA data sho	own is from a different sam	mple or standard on t	he same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services Co., Inc



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number:	2311020136
-----------------	------------

Sample Date : 11/13/23

Collected By: WILLIAM BALENTI

Customer Number: 2853

Customer Name : EUREKA SPRINGS-CREEK @ GASKINS

Sample Time: 1325 Sample Type : GRAB WATER Delivery By : TERRY LONG Work Order :

Report Date : 11/15/23

Sample From : #6 CREEK AT GASKINS

Purchase Order:

n 1 1		Laboratory Analysi	S			Quality 2 Precision	Assurance Accuracy
Analysis <u>Date Time By</u>	Parameter	Result	<u>Notes</u>	Quantity	Method	% RPD	% Recovery
11/13 1630 NTR	E. Coliforms	10.0 /100	ml		06/2012 Colilert18	11.54	N/A *
* QA data sho	wn is from a different sa	mple or standard on	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number:	2311020137
-----------------	------------

11/13 1630 NTR E. Coliforms

Collected By: WILLIAM BALENTI

Customer Number: 2854

Analysis

Date Time By

Customer Name : EUREKA SPRINGS-CR@HWY 187 BRIDGE

Delivery By : TERRY LONG

Sample Type : GRAB WATER

Sample Date : 11/13/23

Sample Time: 1327

Work Order : Purchase Order:

Report Date : 11/15/23

Sample From: #7 CREEK 187 BRIDGE

Quality Assurance Laboratory Analysis Precision Accuracy % Recovery Notes Quantity % RPD 41.0 /100ml 06/2012 Colilert18 11.54 N/A *

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control	Number.	2311020138
COLLCTOT	number.	アンエエハアハエンの

Customer Name : EUREKA SPRINGS-CR@MARTIN MARINE

Sample Date : 11/13/23 Sample Time : 1336 Collected By: WILLIAM BALENTI

Customer Number: 2855

SUREKA SPRINGS-CR@MARTIN MARINE

Sample Type : GRAB WATER

Delivery By : TERRY LONG

Report Date: 11/15/23

Sample From : #8 MARTIN MARINE

Work Order : Purchase Order :

Analysis Date Time By	Parameter	Result	Notes	Quantity	Method 06/2012 Colilert18	Quality Precision RPD 11.54	Assurance Accuracy <u>% Recovery</u> N/A
11/13 1630 NTR	E. Colliforms	104.0 /100	JWT		06/2012 Colliert18	11.54	N/A
)
* OA data sho	own is from a different samp	ple or standard on	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature

Environmental Services Co., Inc



Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com



Environmental Services Company, Inc. Northwest Branch 1107 Century Springdale, AR 72764

CHAIN OF CUSTODY

Phone 479-750-1170 Fax:: 479-750-1172 Phone: 501-221-2565 Fax: 501-221-1341 Requested Parameters Project Information Client Information AR#0021865/ AFIN 08-00036 Permit/Project #: Company Name: Eureka Springs Purchase Order #: Address: 3174 E. Van Buren Eureka Springs, AR 72632 Sampler Name(s): (479) 253-7410 Telephone: FAX: (479) 253-6974 and Signature(s): ESWWTP@YAHOO.COM 1508-Influent ESC Client Number: 1505-Effluent Soli Sample Identification Sample Collection Sample Containers Volume Preservative # ш ESC Control # Date Time Type Matrix Type Identification Sterile 100 m Na₂S₂O₃ 1 Х #1 WWTP & Creek **GRAB** Water 2311020131 36,42014 -93,73453 Sterile 100 m Na₂S₂O₃ 1 X #2 Creek at 835 Hwy 23 N **GRAB** Water 2311020132 36.42497 -93.73669 х **GRAB** Sterile 100 m $Na_2S_2O_3$ #3 Creek at powerline 2311020133 Water -93,73646 36.42518 #4 Creek at Hwy 23 crossing 23 | 1020 | 34 Х $Na_2S_2O_3$ **GRAB** Water Sterile 100 m 36.4398 -93.72906 $Na_2S_2O_3$ Х 2311020135 **GRAB** Water Sterile 100 m #5 Creek upstream 36.42021 -93,73473 Custody Seals Relinquished By: (Signature and Printed Name) Used? Intact? 1405 Turnaround: 1131 Regular Special Received for Lab By: (Signature and Printed Name) Were samples properly preserved: Relinquished By: (Signature and Printed Name) 531 IIIVA KEHU Result Units /FLOW DATA Fjeld Test Time Analyst Result Comments: Analyst: pH; Temp.: Time: DO: Reading: Debris: Units: (1 of 2 Chlorinated? Yes This Document is Page Cool all samples to 6 degrees C.



Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com

Phone: 501-221-2565



Environmental Services Company, Inc. Northwest Branch 1107 Century Springdale, AR 72764

CHAIN OF CUSTODY

Phone 479-750-1170 Fax:: 479-750-1172 Fax: 501-221-1341 Requested Parameters Project Information Client Information AR#0021865/ AFIN 08-00036 Permit/Project #: Eureka Springs Company Name: Purchase Order #: Address: 3174 E. Van Buren Eureka Springs, AR 72632 Sampler Name(s): Telephone: (479) 253-7410 (479) 253-6974 FAX: and Signature(s): ESWWTP@YAHOO.COM 1505-Effluent 1508-Influent ESC Client Number: Coli Sample Identification Sample Collection Sample Containers # Volume Preservative ш Time Matrix Type Identification ESC Control # Date Type $Na_2S_2O_3$ 1 Х **GRAB** Sterile 100 m #6 Creek at Gaskins Water 2311020136 86.426440 -93.443830 х Na₂S₂O₃ #7 Creek at Hwy 187 Bridge 231(020137 **GRAB** Water Sterile 100 m 36.4456 -93.74420 11/13/23 133/ X 100 m $Na_2S_2O_3$ #8 Creek at Martin Marine **GRAB** Water Sterile 36.47349 -93.76037 2311010138 Custody Seals Intact? Used? 17 Date Turnaround Regular Special Were samples properly preserved: Received for Lab By (Signature and Printed Name) 14/13/23 Time 1531 VVV Yes Units Field Test **¢FLOW DATA** Time Analyst Result Result Comments: Analyst: :Ha Temp.: Time: DO: Reading: Units: Debris: This Document is Page (2 of 2 Chlorinated? Yes Cool all samples to 6 degrees C.

