Richard Healey (adpce.ad)

From:Terry Long <eswwtp@yahoo.com>Sent:Tuesday, November 21, 2023 8:27 AMTo:Water-Enforcement-Report; Simon Wiley

Cc: Zane Lewis; Spencer Briggs

Subject: AR 0021865 AFIN: 08-00036 Nov 15 2023

Attachments: BacT sampling Nov 15 2023.pdf

ADEQ Water Enforcement,

Please find the attached lab results with chain of custody from the samples pulled from Leatherwood Creek on Wednesday 11/15/2023.

Moving forward, we continue to collect and analyze samples from the eight (8) locations specified and we will be forwarding those results when received.

If you have any questions, please feel free to contact me.

Thank you,

Terry

Terry Long, Plant Manager Eureka Springs WWTP 100 Highway 23 N. Eureka Springs, AR 72632 479-253-7410 - Office 479-738-7035 - Cell 479-253-6974 - Fax eswwtp@yahoo.com

Eureka Springs WWTP
Eureka Springs Public Works Dept.
3174 E. Van Buren
Eureka Springs, AR 72632
479-253-9600 - Office
479-253-6974 - Fax

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control	Number:	2311020144

Customer Name : EUREKA SPRINGS WWTP @ CREEK

Customer Number: 2856 Report Date : 11/17/23

Sample Date : 11/15/23

Sample Time : 1305

Sample Type : GRAB WATER Sample From : #1 WWTP & CREEK Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order :

Purchase Order:

Analysis		Laboratory Analysi:	3			Quality . Precision	Assurance Accuracy
Date Time By	Parameter	Result	Notes _	Quantity	Method	% RPD	% Recovery
11/15 1645 NTR	E. Coliforms	388.0 /100r			06/2012 Colilert18	0.00	N/A *
•							
* ON data show	wn is from a different samp	le or standard on t	he same	date			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020145

Customer Name : EUREKA SPRINGS-CREEK@835 HWY 23N

Sample Date : 11/15/23

Collected By: WILLIAM BALENTI

Customer Number: 2849

Sample Time: 1114

Delivery By : WILLIAM BALENTI

Sample Type : GRAB WATER

Work Order :

Report Date : 11/17/23

Sample From: #2 CREEK 835 HWY 23N

Purchase Order:

		Laboratory Analysis					<u>Assurance</u>
Analysis Date Time By	Parameter	Result	Notes _	Quantity	Method	Precision 8 RPD	Accuracy % Recovery
11/15 1645 NTR E.	Coliforms	857.0 /10	Oml.		06/2012 Colilert18	0.00	N/A *
						· ·	
							•
* QA data shown i	s from a different sam	ole or standard or	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020146

Sample Date : 11/15/23

Collected By: WILLIAM BALENTI

Customer Name : EUREKA SPRINGS-POWERLINE 1/2 PLT

* QA data shown is from a different sample or standard on the same date.

Sample Time : 1118

Delivery By : WILLIAM BALENTI

Customer Number: 2850

Sample Type : GRAB WATER

Work Order :

Report Date : 11/17/23

Sample From : #3 CREEK POWERLINE

Purchase Order:

4-	, ,	***					
7		Laboratory Analy	sis			<u>Quality</u> Precision	<u>Assurance</u> Accuracy
Analysis	Parameter	Result	Notes	Quantity	Method	% RPD_	% Recovery
<u>Date</u> <u>Time</u> <u>By</u> 11/15 1645 NTR	E Coliforms	697.0 /1	00ml	Qualitity	06/2012 Colilert18	0.00	N/A *
TT/TO TOED MIK	E. COLLIOLING	037.0 71	o o m.s.		00,2022		,
					ł		
					İ		
				.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control	Number.	2311020147
COHEROT	number:	- Z3 TTUZ U T4 /

Customer Name : EUREKA SPRINGS-CREEK@HWY 23 N

Customer Number: 2851 Report Date : 11/17/23 Sample Date : 11/15/23

Sample Time : 1122

Sample Type : GRAB WATER

Sample From : #4 CREEK HWY 23 XING

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order : Purchase Order:

Laboratory Analysis						<u>Assurance</u>
Analysis		And the second s			Precision	Accuracy
Date Time By	Parameter	Result Notes	Quantity	Method	- % RPD	% Recovery
11/15 1645 NTR	E. Coliforms	134.0 /100ml		06/2012 Colilert18	0.00	N/A *

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341 Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762

Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020148

Customer Name : EUREKA SPRINGS-UPSTREAM WWTP

Customer Number: 2852 Report Date : 11/17/23 Sample Date : 11/15/23

Sample Time : 1308

Sample Type : GRAB WATER

Sample From : #5 CREEK UPSTREAM

Collected By: WILLIAM BALENTI Delivery By : WILLIAM BALENTI

Work Order :

Purchase Order:

Report Date . II/I//2	.5	Bampro		OILLEIT OF DELLE			
	<u>Laboratory Analysis</u>					Quality : Precision	<u>Assurance</u> Accuracy
Analysis <u>Date Time By</u>	Parameter	Result	Notes _	Quantity	Method	% RPD	% Recovery
11/15 1645 NTR E. Co		< 10.0 /10			06/2012 Colilert18	0.00	N/A *
· · · · · · · · · · · · · ·							
* QA data shown is	from a different sampl	e or standard on	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020149

Customer Name : EUREKA SPRINGS-CREEK @ GASKINS

Parameter

Customer Number: 2853

11/15 1645 NTR E. Coliforms

Sample Date : 11/15/23

Sample Time: 1325

Delivery By : WILLIAM BALENTI

Collected By: WILLIAM BALENTI

Quality Assurance

Sample Type : GRAB WATER

Work Order :

Purchase Order :

Report Date : 11/17/23

Analysis

Date Time By

Sample From : #6 CREEK AT GASKINS

Laboratory Analysis

Result

Notes < 10.0 / 100ml

Ouantity

06/2012 Colilert18

Precision % RPD 0.00

Accuracy % Recovery N/A

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

06/2012 Colilert18

Control	Number:	2311020150

11/15 1645 NTR E. Coliforms

Customer Name : EUREKA SPRINGS-CR@HWY 187 BRIDGE

Sample Date : 11/15/23

Collected By: WILLIAM BALENTI

Customer Number: 2854

Sample Time: 1126

Delivery By : WILLIAM BALENTI

0.00

N/A *

Report Date : 11/17/23

Sample Type : GRAB WATER Sample From: #7 CREEK 187 BRIDGE Work Order : Purchase Order:

Quality Assurance Laboratory Analysis Precision Accuracy Analysis % RPD % Recovery Result Notes Quantity Method Date Time By Parameter

20.0 /100ml

* OA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Corporate Office 13715 West Markham Little Rock, AR 72211 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch 1107 Century Avenue Springdale, AR 72762 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 2311020151

Sample Date : 11/15/23

Collected By: WILLIAM BALENTI

Customer Name : EUREKA SPRINGS-CR@MARTIN MARINE

Sample Time : 1134

Delivery By : WILLIAM BALENTI

Customer Number: 2855

Work Order :

Report Date : 11/17/23

Sample Type : GRAB WATER Sample From : #8 MARTIN MARINE

Purchase Order:

Analysis		<u> Laboratory Analys</u>	is			<u>Quality</u> Precision	<u>Assurance</u> Accuracy
	77	D =14-	37 - 4	0	no e to be end		
Date Time By	Parameter	Result	Notes _	Quantity	Method	% RPD	% Recovery
11/15 1645 NTR	E. Coliforms	41.0 /10	Oml		06/2012 Colilert18	0.00	N/A *
			. •				
* QA data sho	own is from a different	sample or standard on	the same	date.			

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.



Environmental Services Company, Inc. Corporate Office

13715 West Markham

P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com



Environmental Services Company, Inc. Northwest Branch 1107 Century Springdale, AR 72764

CHAIN OF CUSTODY

Phone 479-750-1170 Fax:: 479-750-1172 Phone: 501-221-2565 Fax: 501-221-1341 Project Information Client Information Requested Parameters Permit/Project #: AR#0021865/ AFIN 08-00036 Company Name: Eureka Springs Purchase Order #: Address: 3174 E. Van Buren Eureka Springs, AR 72632 Sampler Name(s): Telephone: (479) 253-7410 FAX: (479) 253-6974 ESWWTP@YAHOO.COM and Signature(s): ESC Client Number: 1505-Effluent 1508-Influent Coli Sample Identification Sample Collection Sample Containers # Identification ESC Control # Date Time Type Matrix Type Volume | Preservative ші #1 WWTP & Creek Na₂S₂O₃ Х **GRAB** Water Sterile 100 m 1 23/10/20/44 36.42014 -93.73453 11/11/03 #2 Creek at 835 Hwy 23 N 2311020145 **GRAB** Sterile Na₂S₂O₃ Х Water 100 m 36.42497 -93.73669 #3 Creek at powerline 1118 **GRAB** Water Sterile 100 m Na₂S₂O₃ Х 2311020146 36.42518 -93.73646 #4 Creek at Hwy 23 crossing 2311 o 2014 7 11/15/03 1112 $Na_2S_2O_3$ X **GRAB** Water Sterile 100 m 1 36.4398 -93.72906 11/15/13 #5 Creek upstream **GRAB** $Na_2S_2O_3$ Х 2311020148 Water Sterile 100 m 36.42021 -93,73473 Relinquished By: (Signature and Brinted Name) WILLIAM MA Received By: (Signature and Printed Name) Custody Seals: 3:02 303 Ge WILLIAM PALENTINE
(Signature and Printed Name) Used? Intact? 11/15/25 Turnaround: Regular Special Recovered for Lab St. (Signature, and Printed Name) Time "/Date/ 15/23 Were samples properly preserved: Relinquished By: (Signature and Printed Name) Date 1502 Yes Nο FLOW DATA Field Test Time Analyst Result Result Units Comments: Analyst: :Ha \mathcal{C} l'ime: Temp.: DO: Reading: Units: Debris: Cool all samples to 6 degrees C. Chlorinated? Yes No This Document is Page (1 of 2



Envi. ...mental Services Company, Inc. Corporate Office

13715 West Markham


P.O. Box 55146

Little Rock, AR 72211

Little Rock, AR 72215

website: www.esclabs.com

Phone: 501-221-2565



Environmental Services Comp. Northwest Branch 1107 Century Springdale, AR 72764

CHAIN OF CUSTODY

Fax: 501-221-1341 Phone 479-750-1170 Fax:: 479-750-1172 Client Information Project Information Requested Parameters AR#0021865/ AFIN 08-00036 Company Name: Eureka Springs Permit/Project #: Purchase Order #: 3174 E. Van Buren Address: Eureka Springs, AR 72632 WILLIAM BALENTINE Sampler Name(s): (479) 253-7410 Telephone: FAX: (479) 253-6974 ESWWTP@YAHOO.COM and Signature(s): ESC Client Number: 1505-Effluent 1508-Influent Coli Sample Identification Sample Collection Sample Containers # Volume Preservative ESC Control# Date Time Type Matrix Type ші Identification #6 Creek at Gaskins 2311020149 1315 $Na_2S_2O_3$ 1 Х **GRAB** Sterile 100 m Water 36.426440 -93.443830 1726 #7 Creek at Hwy 187 Bridge 2ろ(しのこの) Na₂S₂O₃ Х **GRAB** Water Sterile 100 m 36.4456 -93.74420 11/15/13 #8 Creek at Martin Marine 23/162015 / **GRAB** Sterile 100 m Na₂S₂O₃ Х Water 36,47349 -93.76037 Custody Seals 3:01 11/15/23 3001 11/15/23 - WILLIAM BALTANCE Used? Intact? BALENTINE Turnaround: Regular Were samples properly preserved: Relinquished By: (Signature and Printed Name) Date Received for Lab By: (Signature and Brinted Name) "/15/23 1/11/10 Perru Field Test Units FLOW DATA Time Analyst Result Result Comments: Analyst: pH: Temp.: Time: DO: Reading: Debris: Units: This Document is Page Chlorinated? Yes (2 of 2 Cool all samples to 6 degrees C.

