Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: NPDES Permit No.: AROD 22/10 Monitoring Period (Month/Year): 10 | 20 | 12

No Sanitary Sewer Overflows This Monitoring Period

Allinson

			Summary Report Code Descrip			
Cause(s) of SSO			SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D -Debris	NEAH-No Evide	nce Adverse Health/ Environmental. Impact		CR-Creek/Stream/River (specify)	
E-Equipment Failure	G-Grease	\ OEHC-Observ	red or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch.	
HC-Hydro Clean	LF-Line Failure		K-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet	
R-Rainfall	RG-Roots / Grease	4	4	HR-Hand Rodded	GR-Ground Surface	
RO-Roots	V-Vandalism	- 1		EN-Referred to Engineering	PA-Paved Area	
		* Y		PN-Public Notification	CB-Contained in Building	

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
		,						
							•	
		'						··
		1		• •		•	*	• •
		· i				_		
		şî.						The second second
· · · · · · · · · · · · · · · · · · ·		•						
				the same of the sa	*			was many ways a way and
				The second second				

Signature of Cognizant or Ranking Official

11-20-2013

Date

Lecrtify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

D MOA 5012 1413 F



ADEQ
NPDES Enforcement
5301 Northshore Drive
North Little Rock, AR 72118