

## Sanitary Sewer Overflow Monthly Report

Pictures in Water Drive/Sewer Overflows  
2022

Facility Name: City of Bentonville

Permit # AR0022403 Reporting period April 1-30

No Sanitary Sewer Overflows This Monitoring Period  
Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
C0-Construction	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River
Equipment Failure	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
Rainfall	RG-Roots & Grease	HR-Hand Rodded	GR-Ground Surface
RO-Roots	Vandalism	EN-Referenced to Engineer	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole Number	Start Date of SSO	End Date of SSO	Estimated Volume in Gallons	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
212 Briartown Mews		4/6/2022	4/6/2022	100	LF	NEAH	EC, HC	PA
3608 SE Riviera Rd	486-5073	4/13/2022	4/13/2022	36,000	Rainfall	NEAH	EC	CR
3001 SW Featherston St	483-5594	4/13/2022	4/13/2022	10,000	Rainfall	NEAH	EC	CR

Signature of Cognizant or Ranking Official \_\_\_\_\_ Date \_\_\_\_\_

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

The following information has been sent.

# CONFIRMATION NUMBER

## 29fba00e-a4c5-41f2-873e-6090583db895

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

\*Date Overflow Began:  
4/6/2022

\*Time:  
2:00 pm

Date Overflow Ended:  
4/6/2022

Time:  
4:00 pm

Facility/Permit Information

\*Facility Name:  
City of Bentonville

\*Permit Number:  
AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

The overflow occurred at 212 Briartown Mews. We reported an overflow on 3/29/22 at the same address but the customer has not fixed the issue. The sewer service line that is leaking is a private force main extending from 209 Park St and surfacing at 212 Briartown Mews The city sewer team used a Vac-truck to hydro-excavate to discover that the private force main had been cut and used for a connection for another property. The homeowner was informed and the proper measures are being taken to restore the sewer service. Code enforcement is involved and if the problem is not resolved the water meter will be locked out. (No Water, Can't make sewer)

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other:

Volume of Overflow:  
100

Impact of SSO Overflow Incident  
SSO Affected Private Property (ground)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact  OEEI - Observed or Evidence of Environmental Impact  
 EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment  
 Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

[lshipman@bentonvillear.com](mailto:lshipman@bentonvillear.com)

Additional Comments:

The following information has been sent.

# CONFIRMATION NUMBER

## 0e21ba0b-e6cb-4ce5-be80-b7adcbcc41e3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

\*Date Overflow Began:  
04/13/2022

\*Time:  
9:00 am

Date Overflow Ended:  
4/13/2022

Time:  
3:00 pm

Facility/Permit Information

\*Facility Name:  
City of Bentonville

\*Permit Number:  
AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 3608 SE Riviera Rd. Our lift station could not keep up with the incoming flow due to the heavy rains we had that morning. It is estimated that 36,000 gallons of sewer flowed from manhole 486-5073 to the Osage Tributary 1. Cleaned up what was left of the overflow and spread lime on affected area.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other:

Volume of Overflow:  
36000

Impact of SSO Overflow Incident  
SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill Manhole
- NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded
- Jet-Vac
- Hand Rodded
- Used Generator to Power Pumps/Equipment
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonville.com

Additional Comments:

The following information has been sent.

# CONFIRMATION NUMBER

## 95bf15a4-259a-4854-962f-f78a986e9391

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

### Date/Time Overflow Range

\*Date Overflow Began:

4/13/2022

\*Time:

10:00 am

Date Overflow Ended:

4/13/2022

Time:

1:00 pm

### Facility/Permit Information

\*Facility Name:

City of Bentonville

\*Permit Number:

AR0022403

### Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 3001 SW Featherston St. (South Side of Property) The overflow was due to Heavy rainfall/ I & I. Overflow occurred at manhole 483-5594. It is estimated that 10,000 gallons flowed into Little Osage Tributary 2. Cleaned up what was left from overflow and spread lime on affected areas.

### Description of Problem (check all items that apply)

#### Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

#### Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other:

#### Volume of Overflow:

10000

#### Impact of SSO Overflow Incident

SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)

OEHC - Observed or Evidence of Human Contact  OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment

Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:  
Loran Shipman  
Title:  
Wastewater Collection Supervisor  
Phone:  
4792713140  
Email a Copy of This Report to the Email Address:  
lshipman@bentonvillear.com

Additional Comments: