

## Sanitary Sewer Overflow Monthly Report

Pictures in Water Drive/Sewer Overflows  
2019

Facility Name: City of Bentonville      Permit # AR0022403    Reporting period August 1-August 31  
 Sanitary Sewer Overflows This Monitoring Period  
 Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
C0-Construction	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River
Equipment Failure	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DJ-Ditch
HC-Hydro Clean	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
Rainfall	RG-Roots & Grease	HR-Hand Rodded	GR-Ground Surface
RO-Roots	Vandalism	EN-Referenced to Engineer PN-Public Notification	PA-Paved Area CB-Contained in Building

Location	Manhole Number	Start Date of SSO	End Date of SSO	Estimated Volume in Gallons	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
216 Ridgefield	318-4909	8/3/2019	8/6/2019	10,000	EF,LF	NEAH	EC,HC,HR	CR

Signature of Cognizant or Ranking Official \_\_\_\_\_ Date \_\_\_\_\_

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

# CONFIRMATION NUMBER

**8fa5d548-2d5d-47a0-a963-9d3293571591**

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

\*Date Overflow Began:

8/3/2019

\*Time:

12:00 pm

Date Overflow Ended:

8/6/2019

Time:

12:00 pm

Facility/Permit Information

\*Facility Name:

City of Bentonville

\*Permit Number:

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Over flow occurred at 216 Ridgefield, at the NW corner of property. Overflow location is manhole # 318-4909. There was a blockage between the lift station and the first up stream manhole. I estimate the overflow was between 3gpm and 5gpm. Cleaned up solids and spread lime on the affected area. In my opinion, the overflow occurred due to a failure in the lift station. Discharge flowed down the hill in the back of the property into a spring that flows through the hollow. Volume of overflow is based on pump run times at the lift station and what can be visually seen at the location.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other:

Volume of Overflow:

10000

Impact of SSO Overflow Incident

SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)

OEHC - Observed or Evidence of Human Contact  OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I &amp; I.

Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment  
 Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collections Supervisor

Phone:

(479) 271-3140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments: