

CONFIRMATION NUMBER

17b24a29-b00d-419f-a538-742b02c3d5d0

(NOTE: You will need this number should you ever need to contact ADEC concerning this report)

Date/Time Overflow Range

*Date Overflow Began:

1/24/2021

*Time:

05:00 am

Date Overflow Ended:

1/25/2021

Time:

05:00 pm

Facility/Permit Information

*Facility Name:

City of Bentonville

*Permit Number:

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

The start time of the overflow is an educated guess since we have no way of knowing when this blockage occurred. This overflow occurred at 1114 NW D St at apartment numbers 4 and 7. It was discovered by a member of our team out locating utility lines. The overflow exited through the sanitary sewer private cleanouts at the stated address. The affected areas were confined to a flat ground surface on the north side of these locations. The city sewer team cleaned and televised the city sewer main and found no abnormalities in the city collection system at this location. The Sewer team reached out to the property manager of the apartments and instructed him to resolve the issue and the need of an environmental clean up. The sewer department also contacted the Bentonville code enforcement department so they can follow up on this issue. Estimated overflow at 500 gallons or less.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other: private clean out

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other: paper/wipes

Volume of Overflow:

500

Impact of SSO Overflow Incident

SSO Affected Private Property (ground)

Environmental Damage (check all items that apply)

OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill Manhole NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

Machine Rodded Jet-Vac Hand Rodded Used Generator to Power Pumps/Equipment

Disinfected and Deodorized Hydro Cleaned Spread Lime on Affected Area Public Notification Other: CCTV

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments:

