

Sanitary Sewer Overflow Monthly Report

Pictures in Water Drive/Sewer Overflows
2023

Facility Name: City of Bentonville Permit # AR0022403 Reporting period Dec. 1-31

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	CR-Creek/Stream/River
Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFC-Evidence of Fish Kill	DR-Drop Inlet
Rainfall	RG-Roots & Grease	HR-Hand Rodded	GR-Ground Surface
RO-Roots	Vandalism	EN-Referenced to Engineer	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole Number	Start Date of SSO	End Date of SSO	Estimated Volume in Gallons	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
411 E Central Blvd	362-437	12/15/2023	12/18/2023	5,000	LF	NEAH	WO,EC	GR,CR
303 NW H St	FM	12/26/2023	12/27/2023	500	LF	NEAH	EC	DI

1-2-24

Signature of Cognizant or Ranking Official

Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

The following information has been sent.

CONFIRMATION NUMBER

432f2d22-5ad3-4243-998b-ee86ab4afe80

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:
12/15/2023

*Time:
5:00 pm

Date Overflow Ended:
12/18/2023

Time:
8:30 am

Facility/Permit Information

*Facility Name:
City of Bentonville

*Permit Number:
AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 411 E Central Ave due to an excavator driving over and crushing a shallow clay sewer line. The line segment is between manhole# 362-437 and manhole# 362-442. The line was damaged at approximately 5pm on 12/15/23. The contractor called in the overflow after he arrived at the location on the morning of 12/18/23. Most of the overflow was contained to a grass surface area but some reached the Town Branch Creek. Repaired the broken sewer main and spread lime on effected areas. Overflow estimated at 5000 gallons.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:

Volume of Overflow:
5000

Impact of SSO Overflow Incident

SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill Manhole
- NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded
- Jet-Vac
- Hand Rodded
- Used Generator to Power Pumps/Equipment
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments:

The following information has been sent.

CONFIRMATION NUMBER

a1b1ec75-3739-4194-9ff5-383b3fae3e7d

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:
12/26/2023

*Time:
10:00 am

Date Overflow Ended:
12/27/2023

Time:
4:00 pm

Facility/Permit Information

*Facility Name:
City of Bentonville

*Permit Number:
AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 303 NW H ST due to a private force main servicing 308 N Walton Blvd. Plumber repair break in service. The sewer matter ran down the curb and eventually ran into a ditch at N Walton/NW 3rd St. Overflow estimated at 500 gallons.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:

Volume of Overflow:
500

Impact of SSO Overflow Incident
SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill Manhole NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded Jet-Vac Hand Rodded Used Generator to Power Pumps/Equipment
- Disinfected and Deodorized Hydro Cleaned Spread Lime on Affected Area Public Notification Other: Customer repaired service line.

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments: