

Sanitary Sewer Overflow Monthly Report

Facility Name: City of Bentonville

Permit # AR0022403 Reporting period

January 1-31

2024

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
C0-Construction	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River
Equipment Failure	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
Rainfall	RG-Roots & Grease	HR-Hand Rodded	GR-Ground Surface
RO-Roots	Vandalism	EN-Referenced to Engineer	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole Number	Start Date of SSO	End Date of SSO	Estimated Volume in Gallons	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
206 S Walton Blvd	360-2679	1/2/2024	1/2/2024	500	D	NEAH	EC,HR,HC	DI,GR
806 N Main St	Private	1/28/2024	1/28/2024	2,000	LF	NEAH	WO,EC	GR
1911 SW Nottingham Ave	FM	1/28/2024	1/28/2024	50	LF	NEAH	EC,WO,HC	GR

[Handwritten Signature]

Signature of Cognizant or Ranking Official

Date

2/5/24

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

The following information has been sent.

CONFIRMATION NUMBER

ff83c875-b0c8-4f34-abfc-0eb8ec67549c

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:
1/2/2024

*Time:
1:30 pm

Date Overflow Ended:
1/2/2024

Time:
2:30 pm

Facility/Permit Information

*Facility Name:
City of Bentonville

*Permit Number:
AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 206 S Walton Blvd at manhole# 360-2679. Estimated 500 gallons or less discharged into road flowing into ditch. Blockage was caused by a substantial amount of paper that our team believed came from a newly opened restaurant. Cleared the blockage and hydro-cleaned the road and ditch. Talked to restaurant personnel about the amount of paper they are disposing into the collection system.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:

Volume of Overflow:
500

Impact of SSO Overflow Incident
SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill Manhole
- NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded
- Jet-Vac
- Hand Rodded
- Used Generator to Power Pumps/Equipment
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments:

The following information has been sent.

CONFIRMATION NUMBER

6d4b9d18-89fe-4caf-9f2c-b4b416df7c8f

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:
1/28/2024

*Time:
1:30 pm

Date Overflow Ended:
1/28/2024

Time:
3:30 pm

Facility/Permit Information

*Facility Name:
City of Bentonville

*Permit Number:
AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

806 N Main ST. Customers sewer service had come apart near ditch. Dispatched a crew to assess the issue and decided to connect service back together to stop sewer from flowing out. We are unsure when the issue had started but responded as soon as we were made aware of the issue. Lime was spread over affected area. Property owner and Code Enforcement have been notified of the issue.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:

Volume of Overflow:
2000

Impact of SSO Overflow Incident
SSO Affected Private Property (ground)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill Manhole
- NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded
- Jet-Vac
- Hand Rodded
- Used Generator to Power Pumps/Equipment
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- Other: Repaired Service line and contacted code enforcement.

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Landon McGarrah

Title:

Wastewater Collections Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lmcgarrah@bentonvillear.com

Additional Comments:

The following information has been sent.

CONFIRMATION NUMBER

3ac52ff8-a04e-4450-b536-ca68592c7f7a

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:

1/28/2024

*Time:

11:00 am

Date Overflow Ended:

1/28/2024

Time:

1:30 pm

Facility/Permit Information

*Facility Name:

City of Bentonville

*Permit Number:

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 1911 SW Nottingham Ave due to a break in a force main. Dispatched crew to site. Called in emergency locates. Turned off lift station to stop flow. Cleaned up and removed saturated area with hydro excavation. Excavated area until the broken section of pipe was exposed and prepared for repair. Repaired main. Backfilled excavated area with class 67 around utility and topped with SB2. Returned lift station to full service. No lime was needed after repair was completed.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow

Other: Break in Force Main

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:

Volume of Overflow:

50

Impact of SSO Overflow Incident

SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill Manhole
- NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded
- Jet-Vac
- Hand Rodded
- Used Generator to Power Pumps/Equipment
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- Other: Repaired Force main

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Landon McGarrah

Title:

Wastewater Collections Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lmcgarrah@bentonville.com

Additional Comments: