

Sanitary Sewer Overflow Monthly Report

Facility Name: City of Bentonville

Permit # AR0022403 Reporting period

Pictures in Water Drive/Sewer Overflows
July 1-31

Summary Report Code Descriptions

Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
C0-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River
Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	Vandalism		EN-Referenced to Engineer PN-Public Notification	PA-Paved Area CB-Contained in Building

Location	Manhole Number	Start Date of SSO	End Date of SSO	Estimated Volume in Gallons	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
2301 NE J ST.		7/3/2017	7/3/2017	247,500	LF	NEAH	WO/EC	CR

Nancy Busen Wastewater Utilities Manager
 8-1-2017

 Signature of Cognizant or Ranking Official Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

The following information has been sent.

CONFIRMATION NUMBER

41827cdb-f47e-4237-aabc-fa56d6e9ac0d

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began: 7/3/2017

*Time: 1:00 am

Date Overflow Ended: 7/3/2017

Time: 4:00 pm

Facility/Permit Information

*Facility Name:

CITY OF BENTONVILLE WATER UTILITIES

*Permit Number:

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

20" OF 12" SEWER PIPE WASHED OUT IN THE CREEK BEHIND 2301 NE J STREET. NEAREST MANHOLE IS 320-4863. SEWER FLOWED DIRECTLY INTO THE CREEK.

Description of Problem (check all items that apply)

Type of Overflow

- Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow
 Other: 20" OF PIPE WASHED OUT DUE TO HIGH CREEK LEVEL

Cause of Overflow

- I & I - Rainfall Roots Grease Debris Equipment Failure

- Construction Vandalism Power Failure Line Failure/Break Other:
Volume of Overflow: 247500

Impact of SSO Overflow Incident

SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)