

The following information has been sent.

CONFIRMATION NUMBER

4d168297-2379-4fce-975a-55874a533210

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:

6/11/2018

*Time:

8:00 am

Date Overflow Ended:

6/11/2018

Time:

10:30 am

Facility/Permit Information

*Facility Name:

CITY OF BENTONVILLE

*Permit Number:

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow happened at 1200 NE McClain Rd. due to roots. Overflow occurred at manhole # 321-3232 and spread out in grassy area behind curb. The blockage occurred between manhole number 321-3236 and 321-5476 downstream from the overflow. Used vac truck to suck sewer from around the manhole and spread lime.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:

Volume of Overflow:

200 gallons

Impact of SSO Overflow Incident

SSO Affected Private Property (ground)

Environmental Damage (check all items that apply)

 OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill Manhole NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

 Machine Rodded Jet-Vac Hand Rodded Used Generator to Power Pumps/Equipment
 Disinfected and Deodorized Hydro Cleaned Spread Lime on Affected Area Public Notification Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collections Supervisor

Phone:

479-271-3140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments: