

Sanitary Sewer Overflow Monthly Report

Facility Name: City of Bentonville

Permit # AR0022403 Reporting period August 1- August 31

Pictures in Water Drive/Sewer Overflows
2020

□ Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
C0-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order
Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned
Rainfall	RG-Roots & Grease		HR-Hand Rodded
RO-Roots	Vandalism		GR-Ground Surface
		EN-Referenced to Engineer	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole Number	Start Date of SSO	End Date of SSO	Estimated Volume in Gallons	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
1510 N Walton Blvd	319-3509	8/6/2020	8/6/2020	1,000	RO,G	NEAH	WO,EC,HC	PA
3401 Medlin LN	487-6620	8/25/2020	8/25/2020	500	D	NEAH	WO,EC,HC	PA,GR

Nancy Busen Manager, Water Resource Recovery September 1, 2020
 Signature of Cognizant or Ranking Official Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

CONFIRMATION NUMBER

9d9f9640-b5f7-4a9d-94b0-761bf58f2889

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:

8/6/2020

*Time:

10:00 am

Date Overflow Ended:

8/6/2020

Time:

4:30 pm

Facility/Permit Information

*Facility Name:

City of Bentonville

*Permit Number:

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 1510 N Walton Blvd at manhole 319-3509. The discharge location was in a grassy area on the east side of property, eventually running west through the parking lot to a drainage area. Sewer team cleared the blockage caused by roots, grease, and rags. Washed down the grassy area and parking lot. Sucked all of the sewer matter with the Vac-Truck. Televising today to see if there is a need for further action.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:

Volume of Overflow:

1000

Impact of SSO Overflow Incident

SSO Affected Private Property (ground)

Environmental Damage (check all items that apply)

OEHC - Observed or Evidence of Human Contact OEFI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill Manhole NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

Machine Rodded Jet-Vac Hand Rodded Used Generator to Power Pumps/Equipment

Disinfected and Deodorized Hydro Cleaned Spread Lime on Affected Area Public

Notification Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

479-271-3140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments:

CONFIRMATION NUMBER

4cd6a465-450f-4d53-9267-4affb9484795

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

***Date Overflow Began:**

8/25/2020

***Time:**

2:00 pm

Date Overflow Ended:

8/25/2020

Time:

3:00 pm

Facility/Permit Information

***Facility Name:**

City of Bentonville

***Permit Number:**

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 3401 Medlin Ln at manhole 487-6620. Overflow was caused by a basket that was dumped into the sewer system. Freed the blockage and removed the basket. Cleaned up the sewer matter and spread lime on the affected area around the manhole.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

Construction Vandalism Power Failure Line Failure/Break Other:
Volume of Overflow:

500

Impact of SSO Overflow Incident

SSO Affected Private Property (ground)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental Impact
 EFK - Evidence of Fish Kill Manhole NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded Jet-Vac Hand Rodded Used Generator to Power Pumps/Equipment
 Disinfected and Deodorized Hydro Cleaned Spread Lime on Affected Area Public Notification Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

479-271-3140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments:

