

## Sanitary Sewer Overflow Monthly Report

Facility Name: City of Bentonville

Permit # AR0022403 Reporting period January 1-31  
 No Sanitary Sewer Overflows This Monitoring Period  
 Summary Report Code Descriptions

2022

| Cause(s) of SSO   | SSO Impact   | Action(s) Taken                                     | Ultimate Discharge Location               |
|-------------------|--|---|---|
| C0-Construction   | NEAH-No Evidence of Adverse Health or Environmental Impact | WO-Work Order                                       | CR-Creek/Stream/River                     |
| Equipment Failure | OEHC-Observed or Evidence of Human Contact                 | EC-Environmental Cleanup                            | DI-Ditch                                  |
| HC-Hydro Clean    | LF-Line Failure/Break                                      | HC-Hydro Cleaned                                    | DR-Drop Inlet                             |
| Rainfall          | RG-Roots & Grease  | HR-Hand Rodded                                      | GR-Ground Surface                         |
| RO-Roots          | Vandalism  | EN-Referenced to Engineer<br>PN-Public Notification | PA-Paved Area<br>CB-Contained in Building |

| Location         | Manhole Number | Start Date of SSO | End Date of SSO | Estimated Volume in Gallons | Cause of SSO | Environmental Impact | Action(s) Taken to Address SSO | Ultimate Discharge Location |
|------------------|----------------|-------------------|-----------------|-----------------------------|--------------|----------------------|--------------------------------|-----------------------------|
| 1617 McCollum Rd | N/A            | 1/3/2022          | 1/3/2022        | 500                         | CO           | NEAH                 | EC                             | CR                          |
| 401 SE 2nd St    | 362-431        | 1/18/2022         | 1/18/2022       | 1,000                       | RO           | NEAH                 | EC,HR,HC,WC                    | CR                          |
| 1617 McCollum Rd | N/A            | 1/27/2022         | 1/27/2022       | 440                         | CO           | NEAH                 | WO                             | CR                          |
|                  |                |                   |                 |                             |              |                      |                                |                             |
|                  |                |                   |                 |                             |              |                      |                                |                             |
|                  |                |                   |                 |                             |              |                      |                                |                             |
|                  |                |                   |                 |                             |              |                      |                                |                             |
|                  |                |                   |                 |                             |              |                      |                                |                             |
|                  |                |                   |                 |                             |              |                      |                                |                             |
|                  |                |                   |                 |                             |              |                      |                                |                             |

Signature of Cognizant or Ranking Official \_\_\_\_\_ Date \_\_\_\_\_

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

The following information has been sent.

## CONFIRMATION NUMBER

**4374af8d-9a68-4f54-930b-0667374e758b**

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

### Date/Time Overflow Range

\*Date Overflow Began:

1/3/2022

\*Time:

8:00 am

Date Overflow Ended:

1/3/2022

Time:

4:00 pm

### Facility/Permit Information

\*Facility Name:

City of Bentonville

\*Permit Number:

AR0022403

### Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Address of overflow is 1617 McCollum Rd. This is a new church that is under construction. The sewer line installed for this project has not been accepted by the City of Bentonville. The manhole that the overflow occurred has not been given a manhole number yet. There is no direct connection to the city sewer system. With that being said, the contractor and subcontractors were using a sewer line with no way of draining. The overflow occurred at a manhole west of property leading to a small amount reaching a creek. Our team pumped the sewer matter from the private manhole over to a city owned manhole to stop the issue. Cleaned up sewer matter around manhole and spread lime on the affected area. Contractor was notified and should not happen again.

### Description of Problem (check all items that apply)

#### Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

#### Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other:

Volume of Overflow:

500

Impact of SSO Overflow Incident  
SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact  OEEI - Observed or Evidence of Environmental Impact  
 EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment  
 Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments:

The following information has been sent.

## CONFIRMATION NUMBER

**6d90e199-6567-4e72-a697-3a5fd50fd0ac**

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

### Date/Time Overflow Range

\*Date Overflow Began:

1/18/2022

\*Time:

12:00 am

Date Overflow Ended:

1/18/2022

Time:

10:00 am

### Facility/Permit Information

\*Facility Name:

City of Bentonville

\*Permit Number:

AR0022403

### Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Overflow occurred at 401 SE 2nd St at manhole #362-431. Overflow was caused by roots in the sewer main. Our team used a Vac-truck to free the blockage and our CCTV unit to discover the roots. We used our high pressure cleaning nozzle to chew up the roots. We will have a future work order to repair a bad section of pipe. The overflow came out of the manhole and entered a storm drain inlet that flowed into town branch creek. Our team cleaned up sewer in the road and sucked the sewer out of the storm drain with our Vac-truck. I don't know when this overflow occurred. I am estimating that the overflow was around 1000 gallons.

### Description of Problem (check all items that apply)

#### Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

#### Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other:

Volume of Overflow:

1000

Impact of SSO Overflow Incident  
SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)

OEHC - Observed or Evidence of Human Contact  OEEI - Observed or Evidence of Environmental Impact  
 EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment  
 Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments:

## Loran Shipman

---

**From:** Loran Shipman  
**Sent:** Tuesday, January 18, 2022 12:43 PM  
**To:** Loran Shipman  
**Subject:** 401 SE 2nd St





12:39

LTE

Done

Photo



Sent from my iPhone



The following information has been sent.

## CONFIRMATION NUMBER

**b8e0a8de-ec3c-4569-b6c1-517f7a45ced2**

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

### Date/Time Overflow Range

\*Date Overflow Began:

01/27/2022

\*Time:

5:00 pm

Date Overflow Ended:

01/27/2022

Time:

5:10 pm

### Facility/Permit Information

\*Facility Name:

City of Bentonville

\*Permit Number:

AR0022403

### Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

The address the overflow occurred is 1617 McCollum Dr. I was told by a caller on the phone that a contractor had dumped raw sewer from a 300" discharge hose into a creek west of this property. The discharge hose was 6" in diameter. If the discharge hose was full it had a 440 gallon capacity. The pump was set up for a bypass while the city of Bentonville performed a point repair earlier that day. The caller on the phone said that his boss told him to empty the remaining sewer in the discharge hose in the creek after the city of Bentonville employees left the job. I do not know if this statement is true but I figure I would report just in case.

### Description of Problem (check all items that apply)

#### Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other: discharge hose from pump

#### Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other: Contractor's poor decisions

Volume of Overflow:

440

Impact of SSO Overflow Incident  
SSO Reached Receiving Water (river,stream)

Environmental Damage (check all items that apply)

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill Manhole
- NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded
- Jet-Vac
- Hand Rodded
- Used Generator to Power Pumps/Equipment
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- Other: Did not see any evidence

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collection Supervisor

Phone:

4792713140

Email a Copy of This Report to the Email Address:

lshipman@bentonville.com

Additional Comments: