

Sanitary Sewer Overflow Monthly Report

Facility Name: City of Bentonville

Permit # AR0022403 Reporting period

Pictures in Water Drive/Sewer Overflows
July 1-31

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
C0-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order
Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned
Rainfall	RG-Roots & Grease	HR-Hand Rodded	DR-Drop Inlet
RO-Roots	Vandalism	EN-Referenced to Engineer PN-Public Notification	PA-Paved Area CB-Contained in Building

Location	Manhole Number	Start Date of SSO	End Date of SSO	Estimated Volume in Gallons	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
1500 SE Griffin	446-5618	6/30/2018	7/14/2018	250,000	CO	NEAH	WO,EC,HC	GR

Nancy Buson

8-2-2018

Signature of Cognizant or Ranking Official

Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

The following information has been sent.

CONFIRMATION NUMBER

f9bd4536-72f6-4e89-bc07-9b74c9590fff

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:

6/30/2018

*Time:

9:00 pm

Date Overflow Ended:

7/14/2018

Time:

9:00 pm

Facility/Permit Information

*Facility Name:

City of Bentonville Water Utilities

*Permit Number:

AR0022403

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

The closest address to the overflow is 1500 SE Griffin Dr. The overflow occurred approximately 500" South of the address at manhole number 446-5618. I do not know when the overflow occurred. The time the overflow started and the amount are just an educated guess. It looks like the overflow was caused by a tractor mowing a field and breaking the manhole ring and lid. The broken ring and lid fell into the manhole causing a blockage. This was brought to our attention about 1:30 pm on 7-14-18. We tried rodding the line but we were not successful so we bypass pumped until we were able to free the manhole from all the debris. The sewer did not reach any creek or stream. It is all on the ground so we will load it up and haul it to our Wastewater facility. As I said, I don't have a clue when this started. I estimate the overflow to be 250,000 gallons.

Description of Problem (check all items that apply)

Type of Overflow

Manhole Overflow Lift Station Overflow Main Line Overflow Service Line Overflow Other:

Cause of Overflow

I & I - Rainfall Roots Grease Debris Equipment Failure

- Construction Vandalism Power Failure Line Failure/Break Other: Mower broke manhole ring and lid
 Volume of Overflow: 250,000 gal.
 Impact of SSO Overflow Incident
 SSO Affected Private Property (ground)
 Environmental Damage (check all items that apply)
 OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental Impact
 EFK - Evidence of Fish Kill Manhole NEAH - No Evidence of Adverse Health/Environmental Impact
 Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

- Machine Rodded Jet-Vac Hand Rodded Used Generator to Power Pumps/Equipment
 Disinfected and Deodorized Hydro Cleaned Spread Lime on Affected Area Public Notification Other:
 Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Loran Shipman

Title:

Wastewater Collections Foreman

Phone:

(479) 271-3140

Email a Copy of This Report to the Email Address:

lshipman@bentonvillear.com

Additional Comments: