

Sanitary Sewer Overflow Monthly Report

Facility Name: Paragould Light, Water & Cable - WWTP Permit Number: AR0033766 Reporting Period (Month/Year): May 2018

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		Action(s) Taken	Ultimate Discharge Location
		SSO Impact			
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health of Environmental Impact		WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease			EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	OEHC-Observed or Evidence of Human Contact		HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease			HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism	EFK-Evidence of Fish Kill		EN-Referred to Engineering	PA-Paved Area
				PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in Gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
1609 Rector Road (Lift Station #25)	N/A	05/14/2018	05/14/2018	5,000	LF	NEAH	EC; HC	GR
802 Country Club Road	N/A	05/17/2018	05/17/2018	2,000	LF	NEAH	EC; HC	GR

Daniel Phillips
6-11-2018

Signature of Cognizant or Ranking Official Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."