Sanitary Sewer Overflow (SSO) Monthly Report

the second secon				T 1 1 1 1 1 1	,
Facility Name: City of Corning	Permit Number: AR0033979	Monitoring Period ((Mo/Year): /	-ep/20/4	
				,	

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions							
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location			
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please , specify)			
E-Equipment Failure	-G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch			
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet			
R-Rainfall	RG-Roots & Grease	•	HR-Hand Rodded	GR-Ground Surface			
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area			
			PN-Public Notification	CB-Contained in Building			

Location	Manhole#	Start Date of SSO	End Date of SSO	Estimated Volume (in gailons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
	•					. ,		
	,							
,						(
						ŕ.		
						,		
,								
			·					

Signature of Cognizant or Ranking Official

Date

16-2014

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

City of Corning P.O. Box 538 Corning, Ar 72422



ADEQ NPDES Enforcement 5301 Northshore Drive North Little Rock, AR 72118