

Sanitary Sewer Overflow Monthly Report

Facility Name: The City of Yellville Permit Number: AR0034037 Reporting Period (Month/Year):

May-13

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO		Environmental Impact	Action(s) Taken	Ultimate Discharge Location
CO- Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO- Work Order	CR-Creek/Stream/River (Please Specify)
E-Equipment Failure	G-Grease		EC-Environmental Cleanup	DI-Ditch
HC-HydroCleaned	LF-Line failure/ break	OEHC-Observed or Evidence of Human Contact	HC-Hydro Cleaned	DR-Drop Inlet
	R-Rainfall	EFK-Evidence of Fish Kill	HR-Hand Rodded	GR-Ground Surface
RO-Roots	RG-Roots & Grease		EN-Referred to Engineering	PA-Paved Area
	V-Vandalism		PN-Public Notification	CB-Contained in Building

Location	Manhole#	Start Date of SSO	End Date Of SSO	Estimated Volume (Gal)	Cause of SSO	Environmental Impact	Action Taken to Address SSO	Ultimate Discharge Location

[Handwritten Signature]
Signature of Cognizant or Ranking Official

6-20-2013
Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

City of Yellville
Water Department
P.O.Box 647
Yellville, Arkansas 72687

NORTHWEST AR P&DF
AR 727 2 T
20 JUN 2013 PM



Arkansas Department of Environmental Quality
Enforcement Section/Water Division
5301 Northshore Drive
North Little Rock, AR 72118

7211835317

