

**City of Yellville**  
WATER AND SEWER DEPARTMENT  
P.O. BOX 647  
YELLVILLE, AR 72687  
(870) 449-5210

March 11, 2013

Mr. Dennis Benson  
Enforcement Administrator  
NPDES Enforcement Section  
State of Arkansas  
Arkansas Department of Environmental Quality  
5301 Northshore Drive  
North Little Rock, Arkansas 72118-5317

RE: Arkansas NPDES Permit AR0034037, AFIN 45-000

Dear Mr. Benson,

This letter is to inform you of the City of Yellville's non-compliance with effluent Limitations for the month of February, 2013

1. Description of Violations

- a. NH3-N mg/l, NPDES 7 Day AVG 5.0, Reported 5.3.
- b. NH3-N mg/l, NPDES Max 7.50, Reported 9.4.

2. Reason for Violations:

- a. Due to the motor which drives the main aeration unit going out we had only air going to  $\frac{1}{4}$  of the aeration unit.

3. Duration of the Violation:


- a. The unit was down for approximately 6 days.

4. Corrective Action Taken to Eliminate Violations:

- a. Plant Personnel replaced the motor and a spare motor was order and is in inventory. Upon looking at the next weeks lab analytical data the levels were within limit's.

Thank you for your time and considerations. If you should have any question, please call my office at (870-449-5210).

Sincerely,



Gayle Stude  
City of Yellville

DENNIS BENSON

REPORT OF NON-COMPLIANCE WITH EFFLUENT LIMITATIONS

PERMITEE: YELLVILLE SEWER

PERMIT: AR0034037 001A

REPORTING PERIOD: JANUARY 2013

REPORT DATE: FEBRUARY 2013

---

PARAMETER(S)	NPDES MIN	NPDES AVG	NPDES MAX	RESULT REPORTED	DATE OF EXCURSION
NH3-N mg/L			7.50	9.4	01/13-19/13
NH3-N mg/L		5.00		5.3	*

---

\* Excursion Dates Include: Jan 3rd, 9th, 16th.

COMMENTS:

*Authorized Agent*  
~~PRINCIPAL EXECUTIVE OFFICER~~

TITLE

DATE

*Gayle Stude*  
YELLVILLE SEWER

*Dir. of Public Works*

03-11-2013

**Sanitary Sewer Overflow Monthly Report**

Facility Name: The City of Yellville Permit Number: AR0034037 Reporting Period (Month/Year):

**Feb-13**

**X No Sanitary Sewer Overflows This Monitoring Period**

**Summary Report Code Descriptions**

Cause(s) of SSO		Environmental Impact	Action(s) Taken	Ultimate Discharge Location
CO- Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO- Work Order	CR-Creek/Stream/River (Please Specify)
E-Equipment Failure	G-Grease		EC-Environmental Cleanup	DI-Ditch
HC-HydroCleaned	LF-Line failure/ break	OEHC-Observed or Evidence of Human Contact	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease	EFK-Evidence of Fish Kill	HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole#	Start Date of SSO	End Date Of SSO	Estimated Volume (Gal)	Cause of SSO	Environmental Impact	Action Taken to Address SSO	Ultimate Discharge Location
511 Estes street	1	2/26/2013	2/27/2013	5,000 gal	R	NEAH	HC EC	Town Branch Creek
330 west 8th street	4	2/26/2013	2/27/2013	3,000 gal	R	NEAH	HC EC	Town Branch Creek

*Angela Stude*

03-11-2013

Signature of Cognizant or Ranking Official

Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

City of Yellville  
Water and Sewer Department  
PO Box 647  
Yellville, AR. 72687

72118#5317



Mr. Dennis Benson  
NPDES Enforcement Section  
ADEQ  
5301 Northshore Drive  
North Little Rock, Arkansas 72218-5317

