

**Sanitary Sewer Overflow Monthly Report**

Facility Name: The City of Yellville Permit Number: AR0034037 Reporting Period (Month/Year):

Jul-14

**No Sanitary Sewer Overflows This Monitoring Period**

**Summary Report Code Descriptions**

Cause(s) of SSO		Environmental Impact	Action(s) Taken	Ultimate Discharge Location
CO- Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO- Work Order	CR-Creek/Stream/River (Please Specify)
E-Equipment Failure	G-Grease		EC-Environmental Cleanup	DI-Ditch
HC-HydroCleaned	LF-Line failure/ break	OEHC-Observed or Evidence of Human Contact	HC-Hydro Cleaned	DR-Drop Inlet
	R-Rainfall		RG-Roots & Grease	HR-Hand Rodded
RO-Roots	V-Vandalism	EFK-Evidence of Fish Kill	EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole#	Start Date of SSO	End Date of SSO	Estimated Volume (Gal)	Cause of SSO	Environmental Impact	Action Taken to Address SSO	Ultimate Discharge Location

*Street Officer*  
 Signature of Cognizant or Ranking Official



8-20-2014  
 Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.



**Environmental Services Company, Inc.**

1107 Century  
Springdale, AR 72762  
479-750-1170 Fax: 479-750-1172



ADEQ  
NPDES ENFORCEMENT SECTION  
5301 NORTSHORE DRIVE  
NORTH LITTLE ROCK AR 72218-5317

721185317 R015

