Sanitary Sewer Overflow Monthly Report

Facility Name: Malvern Water Works Permit Number: AR0034126 Reporting Period (Month/Year): Nov. 2012

No Sanitary Sewer Overflows This Monitoring Period Summary Report Code Descriptions				
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (Please Specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism	1	EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Description Ultimate Discharge Estimated Volume Cause of SSO Action(s) Taken End Date of Environmental Manhole # Start Date of Location to Address SSO Location (in gallons) Impact SSO SSO 11/27/12 G JET Rod Work Force (Sullemberger 11/27/12 100 NEA H GR 0109

Signature of Cognizant or Ranking Official

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violation."

Date

12/5/2012

10 DEC 2012 PM3



506 Overman Street P.O. Box 638 Malvern, Arkansas 72104

> ADEQ Water Division - Enforcement Branch 5301 Northshore Drive North Little Rock, AR 72118-5317

9531799

 $H_{indeal}(A_{indeal$