Sanitary Sewer Overflow Monthly Report

Facility Name: Malvern Water Works Permit Number: AR0034126 Reporting Period (Month/Year): 04. 2013

| □ No | Sanitary | Sewer | Overflows | This | Monitoring Period | |
|------|----------|-------|-----------|------|-------------------|--|
|------|----------|-------|-----------|------|-------------------|--|

| | | riptions | · | | |
|---------------------|--|--|----------------------------|--|--|
| Cause(s) of SSO | | SSO Impact | Action(s) Taken | Ultimate Discharge Location | |
| CO-Construction | D-Debris | NEAH-No Evidence of Adverse Health or Environmental Impact | WO-Work Order | CR-Creek/Stream/River (Please Specify) | |
| E-Equipment Failure | G-Grease | IOEHC-Observed or Evidence of Human Contact | EC-Environmental Cleanup | DI-Ditch | |
| HC-Hydro Clean | LF-Line Failure Break | EFK-Evidence of Fish Kill | HC-Hydro Cleaned | DR-Drop Inlet | |
| R-Rainfall | RG-Roots & Grease | | HR-Hand Rodded | GR-Ground Surface | |
| RO-Roots | V-Vandalism | | EN-Referred to Engineering | PA-Paved Area | |
| | terraphy graphic production of the second section of the second s | | PN-Public Notification | CB-Contained in Building | |

Description

| | | • | | Describana | | ₹ , | | |
|--|--------------|--|-----------------|-------------------------------|--------------|-------------------------|--------------------------------|--------------------------------|
| Location | Manhole # | Start Date of SSO | End Date of SSO | Estimated Volume (in gallons) | Cause of SSO | Environmental Impact | Action(s) Taken to Address SSO | Ultimate Discharge Location |
| Jaklama / Oyer St. Interse | erset. 555 | 10/30/13 | 10/30)13 | 50 | G | NEAH | JHRe | GR |
| · · | | | | | | \ | | |
| | | | | | | | | |
| A CONTRACTOR OF THE PROPERTY O | | | | | | | | |
| | | | | | | ì | | |
| <u> معاد حرور داوی و فرد نوار و و همان باید و محمود بود چرخ .</u> | <u> </u> | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | } | · | |
| | | | | | | | | |
| | | | | | <u> </u> | | | |
| <u> </u> | | i | | | | | | |
| | | | | | | | | |
| | | | | | ļ | <u> </u> | | |
| · | | 1 | | <u> </u> | 1 | 1 1 | | <u> </u> |

Signature of Cognizant or Ranking Official

11/1/2013

Date

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violation."


MANGEN WATER WORKS

Soft You.

506 Overman Street
P.O. Box 638
Malvern, Arkansas 72104

LITTLE ROCK AR 772

DIFFIELD ADIS FALSEL



ADEQ Water Division - Enforcement Branch 5301 Northshore Drive N. Little Rock, AR 72118-5317