

Sanitary Sewer Overflow Monthly Report

Facility Name: Pocahontas Water & Sewer Systems Permit Number: AR0034835 Reporting Period (Month/Year): SEPTEMBER 2012.

No Sanitary Sewer Overflow This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action (s) taken	Ultimate Discharge Location
Co-Construction	D-Debris	NEAH- No Evidence of Adverse Health or Environmental Impact	WO-Work Order
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded
R-Roots	V-Vandalism		EN-Referred to Engineering
			PN-Public Notification
			CB-Contained in building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (In gallons)	Cause of SSO	Environment Impact	Action(s) Taken To Address SSO	Ultimate Discharge Location
1501 SPINNERWEBER		09/04/12	09/04/12	100	RG	NEAH	HC	BLACK RIVER
413 MARR		09/24/12	09/24/12	100	RG	NEAH	HC	BLACK RIVER

Signature of Cognizant or Ranking Official *William Weber* OCTOBER 22, 2012

I certify under penalty of law that the document and all attachment were prepared under my direction or supervision in accordance with a system designed to assure that qualified personal properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations.

POCAHONTAS WATER & SEWER SYSTEMS

207 HIGHWAY 67 SOUTH
POCAHONTAS, ARKANSAS 72455
892-3222

MEMPHIS TN 381

26 FEB 2013 PM 5 L



**ADEQ
NPDES ENFORCEMENT DIVISION
WATER DIVISION, ENFORCEMENT SECTION
5301 NORTSHORE DRIVE
NORTH LITTLE ROCK, AR 72118**

72118501790

