


## Sanitary Sewer Overflow Monthly Report

**Facility Name:** TRUMAN Water Works **Permit Number:** AR035602 **Reporting Period (Month/Year):** September 2013  
 **No Sanitary Sewer Overflows This Monitoring Period**

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease		EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	OEHC-Observed or Evidence of Human Contact	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease	EFK-Evidence of Fish Kill	HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location

  
 Signature of Cognizant or Ranking Official

10/10/2013  
 Date


"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

# Trumann Water Works

106 East Main Street  
Trumann, Arkansas 72472-3398

MEMPHIS TN 381

11 OCT 2013 PM 2 L



AR Dept of Enviromental Quality  
NPDES Enforcement Section C  
5301 Northshore Drive  
Little Rock, Ar. 72118-5317

72118531799

