



July 7, 2021

EMAIL

Ms. Sarah Pierce, Enforcement Analyst
Arkansas Division of Environmental Quality
5301 Northshore Drive
North Little Rock, AR 72118-5317

Re: NPDES Permit Number: AR0036692, AFIN: 57-00423, CAO LIS 18-046-001
Progress Report No. 4– SSES Collection System Rehabilitation Plan

Dear Ms. Pierce:

The City of Mena, AR has agreed to provide semi-annual progress reports detailing the progress made towards implementing the collection system rehabilitation plan identified in their Sanitary Sewer Evaluation Survey (SSES), per the Order and Agreement Section of CAO LIS 18-046-001. We offer the following update as Progress Report No. 4:

- During this reporting period, the City of Mena recorded a total of four (4) Sanitary Sewer Overflows (SSOs) within their collection system.
- The City replaced seven (7) sewer service lines, replaced 372 linear feet of sewer main lines, and lined eleven (11) old brick manholes during this period.
- During the months of February-May, Compliance EnviroSystems performed additional flow monitoring as referenced in the City's Collection System Milestone Schedule. The work included installing flow monitors and collecting flow data over the four (4) month period. The flow monitoring report is attached for your reference.

Respectfully Submitted,

HAWKINS-WEIR ENGINEERS, INC.

A handwritten signature in blue ink that reads 'Elizabeth Heiles'.

Elizabeth Heiles, P.E.

ESH/oab

cc: Mr. Charles Pitman, Mena Water Utilities General Manager
Mr. Mike Spencer, Mena Water Utilities Wastewater Superintendent

Attachments: Flow Monitoring Report February – May 2021