Tertify inder real its of law that this document and all attachments were recovered in the control of law that this document and all attachments were recovered in the control of law that this document and all attachments were recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that this document are recovered in the control of law that the c	Constitution of the second of	Date			nohmonte water n	al	Bladure of Gogarzant or Ranking Official (Certify in der menalty of law that the design of the certify in der menalty of law that the design of the certify in der menalty of law that the certific in derivative in deriv	The certify in a substitution in the certification
	25	2-3-	erer Advisor den erez particular de la composition della compositi	والمساورة والمساودة والمساودة والمادة	And an address of the second s	Ma		The same of the sa
						7		
			j. *			· ·	\ *	
· · · · · · · · · · · · · · · · · · ·			\$2.			2	1	and the second s
			,					
arten mustuskistanjungi masa pantuskistanjungi kitangan			*:				, , , , , , , , , , , , , , , , , , ,	
			·			-		and the state of t
						de la companya de la		
			•			4		
					remodel a quantitation of the company of		-	
							-	
	-			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1				in the second se
PA	7	NEAH	R	72,000	1-30-25	1-30-25	5/8	Church & King
0.70	111	114311	B	E 3	1-30-25	1-30-25	9.55	# 7
70	17.6	MEAH	A	000 gh	1-30-25	1-30-25	924	Weiss + Avonit.
Location	Con Con man on	MEAH	R	. C0 000	1-30-25	1-30-25	.615	Church & Raine
Ultho	Action (s) Taken	Environmental	Cause of SSO	Estimated Volume (in gallons)	End Date of	Start Date of	Ranhole #	Location
Simplify of the Community of the Communi	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							Town the same
Confirmed in D. That	an,	-Public Notification	f-Na.		t we will be to the total of th	***		
BA Band Surface		eferred to Engineering	EN-Res	,		وبرست وسواد المارث باست المستقد	V-Vandalism	KO-Roots.
Ch O	+	FR-Hand Roddad					RG-Roots & Grense	
DR-Drop Inlet		FIC-Hydro Cleaned	<b>-</b>	11158 1889 1	in W. 1980 J. 10 applicabilities		Failure/Break	
DJ-Ditch		EC-Environmental Cleanup	r. BC-1	OHHC-Observed or Byidence of Human Contact	served or Byiden	OBJC-O	LR-Line	HC-Hydro Clean
CR-Creek/Stream/River (please specify)	CR-Creek/	WO-Work Order	. EE	Impact finance of Kaverse Health or Environmental	Impact Impact	AD ON-ING BY	Committee	R-Fauinment Ballura
Ultimate Discharge Location	. Oltan	Cheronia) i medi				יייייייייייייייייייייייייייייייייייייי	D-Dahrie	CO-Construction
		A official Tollow	graption8	O Impact	SSO Impact		90	Cause(s) of \$50
1 - manual muundo canseas de seus seus seus seus seus seus seus		oring Period	This Monito	LI NO Sanitary Sewer Overflows This Monitoring Period	atitary Sev	C ON L		, dans a second
100 2025	lonth/Year)	ording Period (Month/Year):	7 100366 92 Repo	mber: 1 Koo.	Formit Number:	1		Teamain Laureni
	8		· •		ia i. ur	>	Maria Illation	Facility Vame. Man
					8			

including the possibility of fine and imprisonment for knowing violations."

information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information,

### 1d42641d-675c-4336-ae86-b054079de19e

Date/Time Overflow Range	
*Date Overflow Began: 1/30/2025	
*Time:	
10:00 am	
Date Overflow Ended:	
1/30/2025	
Time: 8:00 pm	
Facility/Permit Information	
*Facility Name:	
Mena Water Utilities	
*Permit Number:	
Ar0036692	
Location Information	
Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, o as possible.	or other. Be specific
MH # 519 located at intersection of Reine & Church St. ran over into the pavement and ditch	
Description of Problem (check all items that apply)	
Toron of County and	
Type of Overflow	
☑ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:	
Cause of Overflow	
☑ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure	
☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other: Volume of Overflow: 60000	
Impact of SSO Overflow Incident SSO Reached Public Land Only (ground)	
Environmental Damage (check all items that apply)	
☐ OEHC - Observed or Evidence of Human Contact ☐ OEEI - Observed or Evidence of Environmental Impact	
☐ EFK - Evidence of Fish Kill Manhole 💆 NEAH - No Evidence of Adverse Health/Environmental Impact	
Action Taken (check all items that apply)	
Short term and long-term action, including clean-up and any plans to remediate I & I.	
☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment	
☑ Disinfected and Deodorized ☑ Hydro Cleaned □ Spread Lime on Affected Area □ Public Notification □ Other:	
Reported By	
"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance we designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person of manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my kelief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possible imprisonment for knowing violations.	r persons who nowledge and
Name:	
Larry Gross	
Title:	
Maint. Supv.	
Phone: 4793942761	
THE RESIDENCE OF THE PARTY OF T	

#### 763f82dc-c0a1-4d4d-a7e8-e26613316f7b

NOTE: You will need this number should you ever need to contact ADEQ concerning this report)  Date/Time Overflow Range
*Date Overflow Began: 1/30/2025 *Time: 8:00 am Date Overflow Ended: 1/30/2025 Time: 4:00 pm
Facility/Permit Information
*Facility Name: Mena Water Utilities *Permit Number: AR0036692
Location Information
Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.  MH # 924 overflowed at Weiss & Averitt Ave.onto a paved area
Description of Problem (check all items that apply)
Type of Overflow
☑ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:
Cause of Overflow
☑ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure
☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:  Volume of Overflow: 48000  Impact of SSO Overflow Incident SSO Reached Public Land Only (ground)
Environmental Damage (check all items that apply)
☐ OEHC - Observed or Evidence of Human Contact ☐ OEEI - Observed or Evidence of Environmental Impact ☐ EFK - Evidence of Fish Kill Manhole ☑ NEAH - No Evidence of Adverse Health/Environmental Impact
Action Taken (check all items that apply)
Short term and long-term action, including clean-up and any plans to remediate I & I.
☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment ☑ Disinfected and Deodorized ☑ Hydro Cleaned ☐ Spread Lime on Affected Area ☐ Public Notification ☐ Other:
Reported By
"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.
Name: Larry Gross Title: Maint. Supv. Phone: 479-216-1255

1 Email a Copy of This Report to the Email Address:

### 02225761-5a93-49cb-b4d2-0165661da75b

NOTE: You will need this number should you ever need to contact ADEQ concerning this report)
Date/Time Overflow Range  *Date Overflow Began: 1/30/2025  *Time: 8:00 am Date Overflow Ended: 1/30/2025  Time: 3:00 pm
Facility/Permit Information
*Facility Name: Mena Water Utilities *Permit Number: AR0036692
Location Information
Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.  MH # 556 located at the intersection of Reeves Ave & Tyler Ave.overflowed onto the pavement
Description of Problem (check all items that apply)  Type of Overflow
✓ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:
Cause of Overflow
☑ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure
☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:  Volume of Overflow: ◄2,०००  Impact of SSO Overflow Incident  SSO Reached Public Land Only (ground)
Environmental Damage (check all items that apply)
☐ OEHC - Observed or Evidence of Human Contact ☐ OEEI - Observed or Evidence of Environmental Impact ☐ EFK - Evidence of Fish Kill Manhole ☑ NEAH - No Evidence of Adverse Health/Environmental Impact
Action Taken (check all items that apply)
Short term and long-term action, including clean-up and any plans to remediate I & I.
<ul> <li>☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment</li> <li>☑ Disinfected and Deodorized ☑ Hydro Cleaned ☐ Spread Lime on Affected Area ☐ Public Notification ☐ Other:</li> </ul>
Reported By
"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.
Name: Larry Gross Title: Maint. Supv. Phone: 479-216-1255

### 90c16c80-a739-45d7-89ee-82e9fecf517f

Date/Time Overflow Range
*Date Overflow Began: 1/30/2025 *Time: 8:00 am Date Overflow Ended: 1/30/2025 Time:
4:00 pm
Facility/Permit Information  *Facility Name:  Mena Water Utilities  *Permit Number:  AR0036692
Location Information
Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.
MH # 518 located at Church & Reine AVe.overflowed onto the pavement
Description of Problem (check all items that apply)
Type of Overflow
☑ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:
Cause of Overflow
☑ I & I - Rainfall □ Roots □ Grease □ Debris □ Equipment Failure
☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:  Volume of Overflow: 72000 Impact of SSO Overflow Incident SSO Reached Public Land Only (ground)
Environmental Damage (check all items that apply)
☐ OEHC - Observed or Evidence of Human Contact ☐ OEEI - Observed or Evidence of Environmental Impact ☐ EFK - Evidence of Fish Kill Manhole ☑ NEAH - No Evidence of Adverse Health/Environmental Impact
Action Taken (check all items that apply)
Short term and long-term action, including clean-up and any plans to remediate I & I.
<ul> <li>□ Machine Rodded □ Jet-Vac □ Hand Rodded □ Used Generator to Power Pumps/Equipment</li> <li>☑ Disinfected and Deodorized ☑ Hydro Cleaned □ Spread Lime on Affected Area □ Public Notification □ Other:</li> </ul>
Reported By
"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.
Name: Larry Gross
Title: Maint. Supv.
Phone:
479-216-1255 Email a Copy of This Report to the Email Address:  1/31/2025 0.12 Al