## NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality Office of Water Quality – Enforcement Branch 5301 Northshore Drive North Little Rock, AR 72118

RE: Permit No: Ar003	36692	Di	scharge Number: <u>00</u>	)1		
Facility: Mena WWTP						
Address: 323 Polk 53		and a second contract of the second contract of the contract of the second contract of the	santan in ang an ang ang ang ang ang ang ang ang			
City: Mena	and the second s	State: Ar	<b>Zip:</b> 71953			
Contact: M. Spencer		Phone:	4792342592			
Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits		
Monthly Conc.	TSS		15.2	15		
				<b>+</b>		
We feel this problem High Flows/land I						
				· · · · · · · · · · · · · · · · · · ·		
We plan on correcting	g the problem in this man	ner:				
Complete SSES,	start sewer rehab plan.					
				<b>-</b>		
Time estimated that	it will take to correct prob	lem:				
10 Years						
Sincerely,						
molus	22	13Mar19				
Submitted By:		Date				
☐ Submitted	electronically via N	NetDMR				

Certification Statement: I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (Revised March 2016)

## Sanitary Sewer Overflow (SSO) Monthly Report

Monitoring Period (Month/Year): Feb / 2019

Facility Nar	
me: Mena WW	
7	
NPDES Permit	
No.: AR003669	

No Sanitary Sewer Overflows This Monitoring Period

		REPORT CO	REPORT CODE DESCRIPTIONS		
Cause(s) of SSO	of SSO	Environmental Impact	Action(s) T	Taken	Ultimate Discharge Location
C - Construction	<b>D</b> - Debris	EFK - Evidence of Fish Kill	EC - Environmental Cleanup	JV - Jet Vac	GR - Ground
EF - Equipment Failure	G - Grease	OEHC - Evidence of Human Contact	HC - Hydro Cleaned	SL - Spread Lime	CR - Creek / Stream / River (specify)
LF - Line Failure	R - Rainfall (I&I)	OEEI - Evidence of Environmental Impact HR - Hand Rodded	HR - Hand Rodded	DD - Disinfected and	DI - Ditch
PF - Power Failure	RO - Roots	NEAH - No Evidence of Adverse Health or MR - Machine Rodded	MR - Machine Rodded	Deodorized	DR - Drop Inlet
V - Vandalism		Environmental Impact	PN - Public Notification	GP - Used Generator to PA - Paved Area	PA - Paved Area
			EN - Referred to Engineering	Power Equipment	CB - Contained in Building

-	 	 	 	_	 	 	 _	 	
SIM									Starting Location (Address, Intersection, or Manhole #)
									Start Date of SSO
									End Date of SSO
									Estim. Volume (in gallons)
_	9								Cause(s) of SSO
13Mar19				. 次					Environmental Impact
									Action(s) Taken
									Discharge Location

information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the

Date

Signature of Cognizant or Ranking Official