Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Mena	NPDES Permit No.: ar0036692	Monitoring Period (Month/Year): may / 2023				
	No Sanitary Sewer Overflows This Monitoring Period					

REPORT CODE DESCRIPTIONS								
Cause(s) of SSO		Environmental Impact	Action(s) Taken		Ultimate Discharge Locatio			
C - Construction	D - Debris EFK - Evidence of Fish Kill		EC - Environmental Cleanup	JV - Jet Vac	GR - Ground			
EF - Equipment Failure	G - Grease	OEHC - Evidence of Human Contact	HC - Hydro Cleaned	SL - Spread Lime	CR - Creek / Stream / River (specify)			
LF - Line Failure	R - Rainfall (I&I)	OEEI - Evidence of Environmental Impact	HR - Hand Rodded	DD - Disinfected and	DI - Ditch			
PF - Power Failure	RO - Roots	NEAH - No Evidence of Adverse Health or Environmental Impact	MR - Machine Rodded	Deodorized	DR - Drop Inlet			
V - Vandalism			PN - Public Notification	GP - Used Generator to	PA - Paved Area			
			EN - Referred to Engineering	Power Equipment	CB - Contained in Building			

Starting Location (Address, Intersection, or Manhole #)	Start Date of SSO	End Date of SSO	Estim. Volume	Cause(s) of SSO	Environmental Impact	Action(s) Taken	Discharge Location
,							
	_						

Signature of Cognizant or Ranking Official Date

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."