


Sanitary Sewer Overflow Monthly Report

Facility Name: Mena Water Utilities Permit Number: AR0036692 Reporting Period (Month/Year): April 2013
 No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		
		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease	OBHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building


Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
Bert & Weiss	928	4-4-13	4-5-13	300 Gals	R	NEAH	Limed	DI & PA
4th & Sherwood	446	4-4-13	4-5-13	200 Gals	R	NEAH	Limed	DI & PA
3rd & Janssen	448	4-4-13	4-5-13	200 Gals	R	NEAH	Limed	DI & PA



Date
5-1-13

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

MEMA WETP
323 POK 53
MEMA AQ
71953



ADEQ
(NDDER WATER DIVISION)
5301 NORTH SHORE DR
NORTH LITTLE ROCK, AR
72118-5317

