

Sanitary Sewer Overflow Monthly Report
City of Rogers **AR0043397** **Reporting Period: February 2016**
 No Sanitary Sewer Overflow This Monitoring Period

Cause(s) of SSO	Summary Report Code Descriptions					Ultimate Discharge Location
	SSO Impact	Actions Taken	Environment	SSO Impact	Ultimate Discharge Location	
CO - Construction	D - Debris	WO - Work Order	WO - Work Order	CR - Creek/Stream/River (please specify)		
E - Equipment Failure	G - Grease	EC - Environmental Cleanup	DI - Ditch			
HC - Hydro Clean	LF - Line Failure/Break	HC - Hydro Clean	DR - Drop Inlet			
R - Rainfall	RG - Roots & Grease	HR - Hand Rodded	GR - Ground Surface			
RO - Roots	V - Vandalism	EN - Referred to Engineering	PA - Paved Area			
		PN - Public Notification	CB - Contained in Building			

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (gallons)	Cause of SSO	Environ. Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
204 E Glenwood Ave.	2" main line	2/18/2016	2/19/2016	300	LF	NEAH	repaired line /EC	GR

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

[Signature]
 Signature of Cognizant or Ranking Official

March 16, 2016
 Date