## **NON-COMPLIANCE REPORT**

September 24, 2013

Arkansas Department of Environmental Quality NPDES Enforcement Section 5301 North Shore Drive North Little Rock, AR 72118

RE: NPDES Permit No. AR0043613 AFIN No. 14-00059 Discharge Number: 001

Facility: City of Magnolia-Big Creek WWTP

**Physical Address:** 72 Columbia Road 300 Magnolia, AR 71753 **Mailing Address:** P.O. Box 666 Magnolia, AR 71754-0666

**Contact:** Russell Thomas **Phone:** 870-234-2955 **Fax:** 870-234-2203

Email: mwws@sbcglobal.net

Date of Non-compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits	
08/19/2013	Fecal Coliform Bacteria (FCB) 7 DA GEO		800 colonies	400 colonies	
08/27/2013	Fecal Coliform Bacteria (FCB) 30 DA GEO		260 colonies	200 colonies	

## We feel like this problem was due to:

The City owned Water treatment plant discharging backwash water and sludge to our system.

We believe this is causing a shielding affect to our chlorine.

## We plan on correcting the problem in this manner:

Permitting the water system once we have all our analytical data collected for the water treatment plant.

Time estimated that it will take to correct problem:

?

Sincerely

09/24/2013

## Sanitary Sewer Overflow (SSO) Monthly Tabular Report

Facility Name: Magnolia, City of Big Creek WWTP NPDES Permit No.: AR0043613

Monitoring Period (Month/Year):08/_2013	AFIN: 14-0005
Month Year	
No Sanitary Sewer Overflows This M	onitoring Period

Summary Report Code Descriptions						
Cause(s) of SSO		Environmental Impact	Action(s) Taken	Ultimate Discharge Location		
CO-Construction	<b>D</b> -Debris	NEAH-No Evid. of Adverse Health/Environmental Impact	WO-Work Order	CR-Creek/Stream/River (specify		
E-Equipment Failure	G-Grease	OEEI-Observed or Evidence of Environmental Impact	EC-Environmental Cleanup	<b>DI</b> -Ditch		
LF-Line Failure	R-Rainfall	OEHC-Observed or Evidence of Human Contact	HC-Hydro Cleaned	DR-Drop Inlet		
RG-Roots / Grease	RO-Roots	EFK-Evidence of Fish Kill	HR-Hand Rodded	GR-Ground Surface		
V-Vandalism			EN-Referred to Engineering	PA-Paved Area		
			PN-Public Notification	CB-Contained in Building		


Location.	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharg Location
	$\rightarrow$		ll	I.D.				
Signature	Russell	W Moma	A	Da	te ► 09/24/	2013		


Signature of Cognizant Official (sign above)-------Date above (Month/ Day/ Year)-----For ADEQ Staff Use (below)

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Mail to: ADEQ Water Division P.O. Box 8913 Little Rock, AR 72219-8913 Mail NO later than the 25th, of the month following the monitoring period. You should send in the same envelope with the DMR.

City of Magnolia Big Creek WWTP
M P.O. Box 666
Magnolia, AR 71754-0666
Permit # AR0043613
AFIN # 14-00059







<u>Ֆիլիկիիրկանանիիիլիկիրիցիրննվայնդումիիրիգրգ</u>

