#### NON-COMPLIANCE REPORT

January 21, 2016

Arkansas Department of Environmental Quality NPDES Enforcement Section 5301 North Shore Drive North Little Rock, AR 72118

RE: NPDES Permit No. AR0043613 AFIN No. 14-00059 Discharge Number: 001

Facility: City of Magnolia-Big Creek WWTP

Physical Address: 72 Columbia Road 300 Magnolia, AR 71753 Mailing Address: P.O. Box 666 Magnolia, AR 71754-0666

**Contact:** Russell Thomas **Phone:** 870-234-2955 **Fax:** 870-234-2203

Email: mwws@sbcglobal.net

Date of Non-compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
12/08/2015	Ammonia Nitrogen	241.08 lbs		142 lbs, 6.8/13.5 mg/l
12/14/2015	Ammonia Nitrogen	169.05 lbs		142 lbs, 6.8/13.5 mg/l
12/21/2015	Ammonia Nitrogen	238.11 lbs		142 lbs, 6.8/13.5 mg/l
12/01/2015	TSS	456.82 lbs		313 lbs, 15/22.5 mg/l
12/08/2015	TSS	353.88 lbs		313 lbs, 15/22.5 mg/l
12/29/2015	TSS	1,430.64 lbs		313 lbs, 15/22.5 mg/l
12/01/2015	CBOD	250 lbs		209 lbs, 10/15 mg/l
12/08/2015	CBOD	316 lbs		209 lbs, 10/15 mg/l
12/14/2015	CBOD	226 lbs		209 lbs, 10/15 mg/l
12/29/2015	CBOD	399 lbs		209 lbs, 10/15 mg/l

## We feel like this problem was due to:

Increased concentration of sludge being shipped from the water treatment plant, plus high flow through the system

### We plan on correcting the problem in this manner:

Trying to get water treatment plant to cease discharge of its sludge

# Time estimated that it will take to correct problem:

When the water treatment plant ceases discharge of its sludge.

Sincerely,

Russell W. Thomas

01/21/2016 Date

# Sanitary Sewer Overflow (SSO) Monthly Tabular Report

Facility Name: Magnolia, City of Big Creek WWTP NPDES Permit No.: AR0043613
Monitoring Period (Month/Year):12/_2015
A TETRI 14 A GOODEG

AFIN: 14-00059

Month Year

No Sanitary Sewer Overflows This Monitoring Period

		Summary Report Code Descript	tions		
Cause(s) of SSO		Environmental Impact	Action(s) Taken	Ultimate Discharge Locat	
CO-Construction	<b>D</b> -Debris	NEAH-No Evid. of Adverse Health/Environmental Impact	WO-Work Order	CR-Creek/Stream/River (speci:	
E-Equipment Failure	G-Grease	OEEI-Observed or Evidence of Environmental Impact	EC-Environmental Cleanup	<b>DI</b> -Ditch	
LF-Line Failure	R-Rainfall	OEHC-Observed or Evidence of Human Contact	HC-Hydro Cleaned	DR-Drop Inlet	
RG-Roots / Grease	RO-Roots	EFK-Evidence of Fish Kill	HR-Hand Rodded	GR-Ground Surface	
V-Vandalism			EN-Referred to Engineering	PA-Paved Area	
			PN-Public Notification	CB-Contained in Building	

Location.	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discha Location
						_		
		<u> </u>			-			
~ <del>~</del>								
							-	
	<del></del>	100	\	1 -			L	<del></del>

Signature ► Signature of Cognizant Official (sign above)------Date above (Month/ Day/ Year)-----For ADEQ Staff Use (below)

Date ▶ 01/21/ 2016

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing

violations."

Mail to: ADEQ Water Division P.O. Box 8913 Little Rock, AR 72219-8913 Mail NO later than the 25th of the month following the monitoring period. You should send in the same envelope with the DMR.

City of Magnolia Big Creek WWTP P.O. Box 666 -Magnolia, AR 71754-0666 Permit # AR0043613 AFIN # 1400059

> ADEQ **Water Division NPDES Enforcement Section** 5301 North Shore Drive North Little Rock, AR 72118-5317

