NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality NPDES Enforcement Section 5301 Northshore Drive North Little Rock, AR 72118

RE: NPDES	Permit No:	AR0044016	Discharge	Nu

Discharge Number: A - 001-Monthly

Zip:

72519

Facility: ADC- NCU Izard Co Unit

Address: Rt. 5, Hwy. 5N

City: Calico Rock

State: AR

Contact: Chris Ashcraft

Phone:

Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
5/6/2024	Nitrate+Nitrite	9.83lbs/D Day Max		7.5lbs/D Day Max
			4	1999 - Maria Managara, 1999 - Angelander and Angelander and Angelander and Angelander and Angelander and Angela 1999 - Names Angelander and Angelander and Angelander and Angelander and Angelander and Angelander and Angelander

We feel this problem was due to:		
Control Panel + Aeration 5.		0
CARLIND FARATION J	STEM NOT WDIKING	propertue

We plan on correcting the problem in this manner: Restacer narts on the deration sustem and f' tro sane MO 20 , 2024 Mine

Time estimated that it will take to correct the problem/s: Repairs modeles 5 QU ronn

Sincerely, La

Authorized Signature

6-24-2024

Date