

ADEQ FAX 501 682-0880

SANITARY SEWER OVERFLOW (SSO) 24 HR REPORT

Name of Facility: City of Newport	Phone: 870 523-8121
NPDES Permit No: ARO045225	
Date SSO Began: 9-9-18	Date SSO Ended: 9-9-18
Address of SSO 8200 Theatre Drive	

Cl2 contact chamber

- Description
- Manhole Overflow
 - Lift Station
 - Main Line Overflow
 - Service Line Overflow
 - Other - Describe Chlorine contact chamber

Estimated Volume 5000 Gallon

Cause of SSO - Check all that apply

- I and I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Other - Describe Rainfall in Aeration basin overwhelmed Effluent pumps

Action Taken - Check all that apply

- Machine rodded
- Jet-Vac
- Root Saw
- Hand Rodded
- Disinfected and Deodorized
- Spread Lime on Affected Area
- Other - Describe contained within plant perimeter

Environmental Impact

- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEHC - Observed or Evidence of Human Contact
- EFK - Evidence of Fish Kill

Signature: Martin Leonard

Date: 9-12-18