

NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality
Office of Water Quality – Enforcement Branch
5301 Northshore Drive
North Little Rock, AR 72118

RE: Permit No: AR0047384 Discharge Number: 001

Facility: Canfor Southern Pine/Anthony Forest Products Company - Urbana Sawmill

Address: 1236 Urbana Rd

City: Urbana State: AR Zip: 71768

Contact: Carol Austin Phone: 251-452-7174

Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
January 28, 2022	pH	--	4.33	>6 and <9

We feel this problem was due to:

~~Very low rainfall in the area resulted in very little discharge in January, resulting in recirculation of log deck spray water and low pH from the log runoff back into the pond.~~

We plan on correcting the problem in this manner:

~~The pH results for the February 15 and 21, 2022 samples are 6.02 and 6.25 respectively, as more rainfall is returning the pH range to normal.~~

Time estimated that it will take to correct problem:

~~The problem has been corrected.~~

Sincerely,

Carol Austin

February 22, 2022

Submitted By:

Date

Submitted electronically via NetDMR

Certification Statement: I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (Revised March 2016)