

September 11, 2012

CERTIFIED MAIL 91 7199 9991 7030 4904

William King P.O. Box 2008 Texarkana, AR 75504

RE: Failure to Respond

Dear Mr. King:

On July 31, 2012, I sent you a letter concerning the Sanitary System Overflows reported by your facility. The letter requested a written response that includes current issues with the system and the sanitary system management plan (including corrective actions and preventative measures). As of the date of this letter, the response has not been received. Please submit the required response to the inspection to the Department by **September 20, 2012**.

Thank you for your attention to this matter. Should you have any questions, feel free to contact me at 501-682-0636 or you may e-mail me at copenhaver@adeq.state.ar.us.

Sincerely,

Jul

Lindsay Copenhaver Enforcement Analyst Water Division, Enforcement Branch



September 11, 2012

William King P.O. Box 2008 Texarkana, TX 75504

RE: NPDES Permit Number: AR0048691 AFIN: 46-00237 City of Texarkana - North WWTP

Dear Mr. King,

A review of the NPDES file for the above mentioned facility for the period of January 2009 through July 2012 reveals the following compliance issues:

The facility has reported <u>31 Sanitary System Overflows (SSOs)</u>. The primary causes for these overflows have been attributed to grease or large debris such as clothing, towels or rags. The Department is requesting a written response that includes current issues with the system and the sanitary system management plan (including corrective actions and preventative measures).

The facility has also reported <u>6 effluent violations</u> of Part I, Section A. of NPDES Permit No. AR0048691. 3 of the violations were attributed to <u>Flow.</u> A detailed list of the violations has been included with this letter.

Any violation of your NPDES Permit is subject to enforcement action by this Department, pursuant to the Arkansas Water and Air Pollution Control Act. The regulations and your NPDES Permit require that you take all reasonable measures necessary to eliminate or prevent the occurrence of violations. Also, be aware that we maintain records of violations and of non-compliance reports documenting corrective action to determine the appropriateness and level of the enforcement action. **Please submit your written response no later than August 21, 2012.**

Should you have any questions concerning the above referenced compliance issues, please feel free to contact me at 501-682-0636, or you may e-mail me at copenhaver@adeq.state.ar.us.

Sincerely,

Lindsay Copenhaver Enforcement Analyst Water Division, Enforcement Branch

DMR End Date	Oufall	Parameter	Reported DMR Value	Permit Limit
05/31/2009	001-A	Flow, in conduit or thru treatment plant (7 DA AVG, MGD)	1.231	.95
08/31/2009	001-A	Coliform, fecal general (7 DA GEO, #/100mL)	1200	400
10/31/2009	001-A	Flow, in conduit or thru treatment plant (7 DA AVG, MGD)	1.11	.95
12/31/2009	001-A	Flow, in conduit or thru treatment plant (7 DA AVG, MGD)	0.98	.95
03/31/2012	001-A	Solids, total suspended (7 DA AVG, mg/L)	25	22.5
04/30/2012	001-A	Oxygen, dissolved (DO) (INST MIN, mg/L)	5.5	7