

Sanitary Sewer Overflow Monthly Report

Facility Name: City of Texarkana - North WWTP Permit Number: AR0048691 Reporting Period (Month/Year): January 2014

No Sanitary Sewer Overflows This Monitoring Period

Date	Starting Time	Ending Time	Location	Estimated Volume (Gals)	Cause of Overflow	Environmental Impact	Action Taken	Ultimate Discharge Location
01/31/2014	8:29 am	9:35 am	2511 E. 24 th , Texarkana	20	Other - papers	NEAH	WO, HC, TR	GR

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO - Construction	D - Debris	NEAH - No Evidence of Adverse Health or Environmental Impact	WO - Work Order	CR - Creek/Stream/River (Please specify)
E - Equipment Failure	G - Grease	OEHC - Observed or Evidence of Human Contact	EC - Environmental Cleanup	DI - Ditch
RO - Roots	V - Vandalism	EFK - Evidence of Fish Kill	HC - Hydro Cleaned	DR - Drop Inlet
LB - Line Break	U - Unknown		TR - Treated with Enzymes	GR - Ground Surface
			EN - Referred to Engineering	PA - Paved Area
			PN - Public Notification	CB - Contained in Building

Signature of Cognizant or Ranking Official _____

Date February 11, 2014

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

Sanitary Sewer Overflow Monthly Report


Facility Name: City of Texarkana - North WWTP Permit Number: AR0048691 Reporting Period (Month/Year): January 2014

No Sanitary Sewer Overflows This Monitoring Period

Date	Starting Time	Ending Time	Location	Estimated Volume (Gals)	Cause of Overflow	Environmental Impact	Action Taken	Ultimate Discharge Location
01/31/2014	8:29 am	9:35 am	2511 E. 24 th , Texarkana	20	Other - papers	NEAH	WO, HC, TR	GR

Summary Report Code Descriptions			
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO - Construction	D - Debris	NEAH - No Evidence of Adverse Health or Environmental Impact	WO - Work Order CR - Creek/Stream/River (Please specify)
E - Equipment Failure	G - Grease	OEHC - Observed or Evidence of Human Contact	EC - Environmental Cleanup DI - Ditch
RO - Roots	V - Vandalism	EFK - Evidence of Fish Kill	HC - Hydro Cleaned DR - Drop Inlet
LB - Line Break	U - Unknown		TR - Treated with Enzymes GR - Ground Surface
			EN - Referred to Engineering PA - Paved Area
			PN - Public Notification CB - Contained in Building


Signature of Cognizant or Ranking Official _____





Date February 11, 2014

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

CERTIFIED MAIL™



7011 2970 0001 7184 2811



Texarkana Water Utilities

801 Wood Street, P.O. Box 2008
Texarkana, Texas 75504

Arkansas Department of
Environmental Quality
NPDES Enforcement Section
5301 N. Shore Dr.
North Little Rock, AR 72118-5317

