Sanitary Sewer Overflow Monthly Report

Facility Name: Clinton Water & Sewer Permit Number: AR0048836 Reporting Period (Month/Year): March 2015

□ No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)	
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch	
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet	
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface	
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area	
			PN-Public Notification	CB-Contained in Building	

	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
930 GARY St Clinton AR	5-100	3-19-205	3-20-2015	3000	R	NEAH	EC - Line Deaders	DI
				· · · · · · · · · · · · · · · · · · ·				<u> </u>
								······
								· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·				-			
		······································		, <u></u> , <u>_</u> , <u></u>		· · · · · · · · · · · · · · · · · · ·		allans Malana en e

4-18-2015 Date

Signature of Cognizant or Ranking Official

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. REPORT OF NON-COMPLIANCE WITH EFFLUENT LIMITATIONS

PERMITEE: CLINTON, DW BACKWASH

REPORTING PERIOD: JAN - MAR 2015

PERMIT: ARG640085 001

REPORT DATE: MARCH 2015

NPDES NPDES NPDES RESULT DATE OF PARAMETER(S) MIN AVG MAX REPORTED EXCURSION Al Diss. mg/L 2.00 9.6400 01/07/15 Al Diss. mg/L 01/04-10/15 2.00 9.6400 Al Diss. mg/L 1.00 9.6400

* Excursion Dates Include: Jan 7th.

COMMENTS:

Working with Engineering at this time to Resolve this issue.

PRINCIPAL EXECUTIVE OFFICER

CLINTON BACKWAS TITLE

DATE

13-1012

ADEQ - Water Div - NPDES - 24-Hour Sanitary Sewer Overflow Report Confirmation P... Page 1 of 1

÷

CONFIRMATION NUMBER

78C0898F-37C1-44C6-858A-07CF13490FF6

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 78C0898F-37C1-44C6-858A-07CF13490FF6
Date Sent: 3/20/2015

SSO Bypass U Facility Permit Number: Date Overflow Began:	lpset AR0048836 03/19/2015	Facility name: Time:	Clinton water and sewer 2:00 pm				
Date Overflow Ended:	03/20/2015	Time:	11:00 am				
Location:	Corner of Gary ST. and Nell Jo St Overflow went into yard and ditch						
				Å			
			. ·	\sim			
	(Give address, manh	ole number-if numbered. Incl	ude where the overflow went-yard, ditch, stream, storm sew	er, building, other).			
Type of Overflow			Cause of Overflow				
() Manhole Overflow			(🗹) I & I - Rainfall				
() Lift Station Overflow	1		(D) Roots				
() Main Line Overflow			() Grease				
() Service Line Overflo			(🗋) Debris				
(🗍 Other Overflow Type			(🗆) Equipment Failure				
	(Enter overflow type if	not listed)	(🗆) Construction				
Volume:	3000		(\Box) Vandalism				
	(Give an estimate in ga	allons)	(🗆) Power Failure				
Impact of SSO Event:	SSO Affected Private	Property (ground)	(🗆) Line Failure/Break				
1			(🗆) Other Cause:				
Action Taken - Check all that	a a a lu						
		up and any plans to remediate	• 1 & 1).				
() Machine rodded		(🗹) Disinfected and Deodo					
(\Box) Jet-Vac		(]) Hydro Cleaned					
(🗆) Hand rodded		(2) Spread Lime on Affect	ed Area				
(🗆) Used Generator To P	ower Pumps/Equipment	() Public Notification					
() Other: Describe		(
Environmental Damage							
() OEHC - Observed or			idence of Adverse Health/Environmental Impact				
(L) OEEI - Observed or I	Evidence of Environmenta	al Impact (□) EFK - Evidenc	e of Fish Kill				
Reported By Roy Keeling		Title Manager	Telesters di la dina menera				
in the state of the second		Title Manager	Telephone Number (501) 745-4320				
Additional Comments if Ne	eded:						
				×			
				8			
J	16.1 MARATAN AND AND AND AND AND AND AND AND AND A			<u>x</u> i			

Email a Copy of This Report to the Email Address: clintonwater@clintoncable.net $\vec{V}_{\rm c}$

Clinton WAter P.O. Box 277 Clinton AR. 72031



H.D.E.Q. ENFORCEMENT Section/WATER Division/ 530/ North shore DR. North Little Rock, AR 72/18