NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality NPDES Enforcement Section 5301 Northshore Drive North Little Rock, AR 72118

RE: NPDES Permit No:	AR0048836	Discharge Number:	001

Facility: Clinton, East 001

Address: Factory Road

____State: AR____Zip: <u>72031</u>____ Clinton City:

Contact: Richard McCormac Phone: (501)-745-4320

Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
11/16/2022	Cadmium	<17.8 lbs/day		0.02 lbs/day
11/30/2022	Fecal Coliform		>2419.6 CFU	2000.0 CFU

We feel this problem was due to: Light Bank was bad. Had two Found One UV ballast out also.

We plan on co			is manner:		10	10 00
Represe	ntative	trom	Irojan	Came 1	on 12	-19-22
Repaired	One L	IV Bank	actim	a four	U.V. ligh	+ back
aping	Two bal	last stil	Pout	but we	haven	order five
ballast.	Should	leave	Three	on the	selfe	for future
			A			3

Time estimated that it will take to correct problem: Most of the repair has NPILS

Sincerely,

-2 MG Authorized Signature

- 20-22