

Sanitary Sewer Overflow Monthly Report

Facility Name: Clinton **Permit Number:** AR0048836 **Reporting Period(Month/Year):** Nov 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
<u>Thomas St.</u>	<u>4</u>	<u>11/17/2015</u>	<u>11/18/2015</u>	<u>3000</u>	<u>I & I</u>	<u>NEAH</u>	<u>Limed AREA</u>	<u>Ditch IN AREA</u>

Roy Kelly
 Signature of Cognizant or Ranking Official

12-22-2015
 Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0DA4C27C-94E4-4532-B37C-6251ABE40A3E

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0048836

Facility name:

Clinton

Date Overflow Began:

11/17/2015

Time:

3:30 pm

Date Overflow Ended:

Time:

Location:

Thomas Street Clinton AR. Sub Area 100 Manhole 4. This is a low lying area overflow is in yard ar ditches.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer,

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

3000

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Roy Keeling Title Manager Telephone Number (501) 745-4320


Additional Comments if Needed:

At this time there is a proposed 10 year plan that has been brought before the city council that addresses the current I&I problems. This plan includes the use of camera system to locate the affected area's and for the repair / replacement of damaged

Email a Copy of This Report to the Email Address:

clintonwater2@gmail.com

Clinton Water & Sewer
P.O. Box 277
Clinton AR. 72031



US POSTAGE
\$00.92⁵
First-Class

Mailed From 72031
12/22/2015
032A 0061814271

ADEQ
Enforcement Section/Water Division
5301 Northshore Dr.
North Little Rock, AR 72118